

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30843
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857948
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No.	142
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3993' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
15 SMITH RD, MIDLAND, TX 79705

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 2628 Feet From The WEST Line
Section 1 Township 18S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3993' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: PERF, ACID STIM ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-28-07: MIRU.
10-01-07: TIH W/WS TO 3525. TIH & TAG @ 4582. MILL OUT JUNK FR 4582-4592.
10-02-07: TIH W/KILL STRING TO 2500.
10-03-07: PU BHA & TIH W/WS TO 3822. TIH W/SHOE TO TAG @ 4595. CUT OVER JUNK FR 4595-4597.
10-04-07: TIH W/NEW SHOE, BHA TO 3822. TIH TO TAG @ 4597'.
10-05-07: GIH W/NEW BIT & TAG @ 4595. CUT OVER JUNK FR 4595-4602.
10-08-07: TIH W/BIT TO TAG @ 4590. FELL THRU & TIH TO 4602. DRILL 4602-4900.
10-09-07: SPOT ACID 4887-4680 W/10 BBLS & FLUSH W/29 BFW. PERF 4614-4846. TIH W/2 7/8" WS TO 2500.
10-10-07: TIH W/PKR & SET @ 4087. PMP 10,000 GALS 15% HCL.
10-11-07: RU SWAB.
10-12-07: REL PKR. TIH W/BIT TO TAG BAD CSG @ 4590. FELL THRU TO TAG FILL @ 4772.
10-15-07: PU NEW BIT & TAG @ 4803. C/O 4803-4900.
10-16-07: PU BHA. TIH W/2 7/8" TBG.
10-17-07: TEST RUN SUB PMP- GOOD. RIG DOWN. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist DATE 10/25/2007

TYPE OR PRINT NAME Denise Pinkerton Telephone No. 432-687-7375

(This space for State Use)

APPROVED [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER
CONDITIONS OF APPROVAL, IF ANY:

DATE

OCT 30 2007