

Submit 3 Copies To Appropriate
District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21843
5. Indicate Type of Lease X STATE FEE
6. State Oil & Gas Lease No. B-9385
7. Lease Name or Unit Agreement Name New Mexico -AN- State
8. Well Number 010
9. OGRID Number 213190
10. Pool name or Wildcat Saunders

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: X Oil Well Gas Well Other (Injection)
2. Name of Operator CrownQuest Operating, LLC
3. Address of Operator Box 53310, Midland, TX 79710
4. Well Location (Surface) Unit Letter E ; 1980 feet from the North line and 660 feet from the West line Section 22 Township 14S Range 33E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.):
4213' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON
TEMPORARILY ABANDON ☒ CHANGE PLANS
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING ☐
COMMENCE DRILLING OPNS PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB
OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MI RU PU. NU BOP. Notify OCD of work 24 hrs prior to commencing.
2. PU 2-7/8" work sting & RIH w/ casing scraper. POH.
3. RIH w/ 5.5" 17# CIBP & set @ 9700'. PU 1 joint of tubing.
4. RU one pump truck loaded w/ 110 bbls 2% KCl & one transport loaded w/ 120 bbls 2% KCl water.
5. Pump water from transport first through pump truck, and hook return line to transport. DO NOT ALLOW ANY WATER TO TOUCH GROUND!!
6. Circulate hole clean.
7. Run MIT & keep a chart for the OCD.
8. POH & LD tubing.
9. RD MO PU.
10. Send chart along with Sundry notice to the OCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE: 10-30-07

Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381

(This space for State use)

APPROVED BY Gary W. Wink
Conditions of approval, if any

OC FIELD REPRESENTATIVE W/STAFF /MANAGER DATE NOV 19 2007

Conditions of Approval for TA: the operator shall give 24 hour notice the the appropriate District office before work begins.