

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-0-25-25193
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-3218
7. Lease Name or Unit Agreement Name LARIO STATE #1
8. Well Number #1
9. OGRID Number 153427
10. Pool name or Wildcat BAR "N" PENN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
GUADALUPE OPERATING LLP

3. Address of Operator
1407 W. CUTHBERT AVE MIDLAND, TX 79701

4. Well Location
Unit Letter O : 660 feet from the SOUTH line and 1,874 feet from the EAST line
Section 1 Township 9S Range 32E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PANDA ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Set CIBP at 9,025' & dump bail 4 sx cmt on top.
- Set 100' cmt plug (25 sx) 5,747' - 6,000'.
- Perforate 5 1/2" csg at 3,700'. Set packer at 3,499'. Could not pump into Perfs at 3,700' - spotted 38 sx cmt from 3,334' - 3,767'. WOC. Tag cmt at 3,334'.
- Set 25 sx cmt plug 1,714' - 1,967'. Did not tag.
- Perforate 5 1/2" csg at 474'. Attempt to pump into formation. Could not pump - in. Set 25 sx cement plug from 374' - 474'. Tagged cmt plug at 413'. Spotted 10 sx cement plug 96' - surface.
- Well plugged & abandoned 7/02/2007. Cut wellhead off & cut casing off 5' below ground level. Welded marked on top of csg.
Note: All revisions to original procedure were discussed with, approved & witnessed by Mr. Maxey Brown, OCD Representative.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy D. Triche TITLE Production Mgr DATE 7-2-2007

Type or print name
For State Use Only

E-mail address: byud@aoe.com

Telephone No. 432-553-2856

APPROVED BY: Hay W. Wink

OC FIELD REPRESENTATIVE II/STAFF MANAGER
TITLE _____

DATE NOV 27 2007

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

Conditions of Approval (if any):