Submit 3 Copies To Appropriate District Office State of New Mexico	•
District 1 Energy, Minerals and Natural Resources WELL API NO. WELL API NO.	
District II  1301 W Grand Ave., Artesia, NM 88210  District III  1320 South St. Eropeia Dr.  1320 South St. Eropeia Dr.	
1000 Rio Brazos Rd , Aztec, NM 87410 STATE FEE STATE	
District IV 1220 S St Francis Dr , Santa Fe, NM 87505  Santa Fe, NM 87505  6. State Qil & Gas Lease No. LH 1840	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)  7. Lease Name or Unit Agreement Name  Corbin State	
1. Type of Well: Oil Well  Gas Well Other  8. Well Number	
Name of Operator     EOG Resources, Inc  9. OGRID Number	
3. Address of Operator 10. Pool name or Wildcat	
P.O. Box 2267, Midland, TX, 79702 West Corbin (Delaware)  4. Well Location	
Unit Letter F: 1980 feet from the North line and 1980 feet from the West line	
Section 16 Township 18-S Range 36-E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3887 GL  Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL F Sect 16 Twp 18S Rng 35E Pit type Steel Depth to Groundwater 100 Distance from nearest fresh water well Over 1000	, )'.⊇
Distance from nearest surface water Below-grade Tank Location UL Sect Two Rng :	521
1980 feet from the North line and 1980 feet from the West line (Steel Tank)	\$ 25
12 Chook Ammonisto Danas Indian No.	S.
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND	
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
1. Set 5 1/2 CIBP @ 6510', cap W/25sx Class C CMT WOC Tap @ 6277  Approved as to plugging of the WAT Page	
2. Pick up tubing to +/- 4260 Spot 30sx cmt plug. 3. Pick up tubing to +/- 3050 Spot 30sx cmt plug. Tag @ 2792 CSG Shoe @ 3000. 4. Pick up tubing to +/- 1690 Spot 25sx cmt plug. 5. Pick up tubing to +/- 1690 Spot 25sx cmt plug. 5. Pick up tubing to +/- 4050 Spot 25sx cmt plug.	<b>)</b>
5. Pick up tubing to +/- 405 Spot 40sx cmt plug to surface. 6. Cut casing 3' below surface, weld plate and abandonment marker to casing. Clean location and restore location. P&A Complete 8-24-05	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURETITLE Consultant DATE 8-24-05	
Type or print name E-mail address: Telephone No. 432-561-8600	
(This space for State use) SEP 0 7 2005	
APPPROVED BY AMAGERDATE  Conditions of approval, if any  TITLE  TITLE  TITLE	[ ]
APPPROVED BY CAME OF TITLE  Conditions of approval, if any  OC FIELD REPRESENTATIVE 11/STAFF MANAGER DATE  OC FIELD REPRESENTATIVE 11/STAFF MANAGER DATE	. NVW
APPPROVED BY CAUTE. WINK TITLE  Conditions of approval, if any  OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE  OL to Release  11/27/2007	7