Submit 3 Copies To Appropriate District	State of New Mo	exico	Form C-103
Office District I	Energy, Minerals and Natural Resources		WELL API NO
1625 N French Dr., Hobbs, NM 88240	-		30 075 76731
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St. Francis Dr., Santa Fe, NM			L5393
87505	CES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Getty 6 State Com
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 1
2. Name of Operator			9. OGRID Number 25078
Whating Oil and C728 Corp. 3. Address of Operator			10. Pool name or Wildcat
400 W. Illinois, Ste. 1300, Midland Tx 79701		North Berry Bone Springs	
1/1 Well Location			
Unit Letter 2500 feet from the 1107 4u mile and 200 feet from the			
Section 6 Township 215 Range 34E NMPM LED County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3753' GR			
Pit or Below-grade Tank Application or Closure Pit typewkov Depth to Groundwater 100 Distance from nearest fresh water well Distance from nearest surface water No.			
Pit type wkov Depth to Groundw	ater LOO Distance from nearest fresh	water well Dis	onstruction Material YOU
Pit Liner Thickness: 2 mil Below-Grade lank: Volume 50 bols, Constitution			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO:	SUE REMEDIAL WOF	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK P PLUG AND ABANDON REMEDIAL WORK ALTERING CASING L TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	CARINO CEMENT ICE		
OTHER.	П	OTHER.	
The Completed exercising (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we hoose diagram of proposed completions.			
or recompletion.			
Rig up PU; unhaus well, unset pump. Back off rods, install BOP.			
Run CH loss.			
Run CH loss. Add perfs in producing yone; frac w/60,000 galo gel.			
Run tebing, pump. rods.			
Run teeting, pu	mpi rous.	•	
Place well back	. on production.		
	shove is this and complete to the	best of my knowled	ge and belief. I further certify that any pit or below-
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or classed according to NMOCD guidelines . a general permit or an (attached) alternative OCD-approved plan .			
SIGNATURE MANAGE		Regulatory Cher	<i>i i</i>

Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will/be constructed or closed according to NMOCD guidelines [2], a general permit of an (attached) alternative OCD-approved plan of the constructed or closed permit of an (attached) alternative OCD-approved plan of the constructed or closed permit of an (attached) alternative OCD-approved plan of the constructed or closed plan of the constructed or closed plan of the constructed or closed permit of an (attached) alternative OCD-approved plan of the constructed or closed plan of the closed plan of the