Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District 1	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-025-28468
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		VA-928
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		State NO
1. Type of Well: Oil Well Gas Well Other SWD X		8. Well Number 1
2. Name of Operator		9. OGRID Number
Ray Westall	5	018862
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4, Loco Hills NM, 88255		Wildcat
4. Well Location		
Unit Letter E: 1980 feet from the North line and 660 feet from the West line		
Section 7		NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application □ or Closure □		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: Convert to SWD	☐ OTHER:	·
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Convert to injection according to the SWD-977 A Pull existing tubing. Go in hole with plastic lined tubing and packer, set at approximately 6350'. Received Hobbs OCD Received Hobbs OCD Received		
Convert to injection according to the SWD-977 A		
Pull existing tubing. Go in hole with plastic lined tubing and packer, set at approximately 6350'.		
Test casing.		
Hope 2		
		LE L
		18 18 TE 18 1
		/2c SS120c.
\		
	$-\mathcal{A}$	
I hereby certify that the information	A it was and a small start at the best of the second	, , , , , , , , , , , , , , , , , , ,
I hereby certify that the information that he is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.		
	Guidennes Li, a general per mit	(minerica) and nauve OCD-approved high [].
SIGNATURE //////	TITLE Geologist	DATE_11/2/07
	10 T	
Type or print name Randall Harris E-mail address: rharrisnm@aim.com Telephone No.505.677.2370		
For State Use Only		
ADDROVED DV. GWW		
ADDDAVED DV. (2) VV VV	TITI E	DATE