Submit 3 Copies To Appropriate District Office <u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240	State of New Mer Energy, Minerals and Natur	WELL API NO.	_	C-103 27, 2004		
District II 1301 W. Grand Ave , Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		 5. Indicate Type STATE [6. State Oil & Ga 	of Lease ⊠ FEE □	5-26857	
1220 S St Francis Dr , Santa Fe, NM 87505	ES AND REPORTS ON WELLS		7. Lease Name or	B-139	-	
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS)	East Vacuum	GB/SA Unit Tra				
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			8. Well Number	002	-	
2. Name of Operator			9. OGRID Numb			
ConocoPhillips Company ATTN: Celeste Dale 3. Address of Operator			10. Pool name or	21781 Wildont	/	
3303 N. "A" Street, Bldg. 6 #247, Midland, Texas 79705-5406			Vacuum GB/			
4. Well Location				<u> </u>	/	
Unit LetterO:_5	50_ feet from theSouth	line and2,470	_feet from the	East line		
Section 19	Township 17-S	Range 35-E	NMPM	County	Lea	
	11. Elevation (Show whether DR, 3,988' GR 3,999' RK	,				
Pit or Below-grade Tank Application 🛛 or (Closure					
Pit typeSTEEL Depth to Groun	dwater Distance from nearest fresh	n water well Distan	ce from nearest surfac	e waterN/A		
Pit Liner Thickness: STEEL mil	Below-Grade Tank: Volume	180bbls; Co	onstruction Material	STEEL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT F					_	
	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASI	NG	
		COMMENCE DRIL	_	P AND A	L]	
PULL OR ALTER CASING		CASING/CEMENT OTHER:	JOB []			
13. Describe proposed or comple	ted operations. (Clearly state all p k). SEE RULE 1103. For Multiple	ertinent details, and				

SEE ATTACHED CURRENT & PROPOSED PLUGGED WELLBORE DIAGRAMS & PROCEDURE

.

THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or grade tank has been/will be constructed or classed according to NMOCD guidelines 🖾, a general permit 🗋 or an (attached) alternative OCD-approved plate	below- in 🔲.
SIGNATURE	<u>07</u>
Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-	1994
DEC 0 6 APPROVED BY: Conditions of Approval (if any):	2007

WELLBORE SKETCH

ConocoPhillips Company - Lower 48 - Mid-Continent BU / Permian Operations





ConocoPhillips Company

Proposed Plugging Procedure

East Vacuum Grayburg/San Andres Unit 1911#002 API #30-025-26857 East Vacuum GB/SA Unit Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

4½" 11.6# casing @ 4,800' (TOC @ surface); no tubulars in hole; <u>SALT DEPTHS</u>: Top @ 1,870'; Base @ 2,819'.

- Verify anchors tested within last two years
- Notify NMOCD & BLM 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537) minimum 48 hrs prior to move-in
- TA'd (06/11/07) w/ 4½" RBP's @ 4,470' & 2,005', isolated casing leak above 10' (casing tested to 500 psi below 10'. Hole circulated w/ 10 ppg brinewater.
- 1. Set steel pit and flow down well as needed. Deliver 4,600' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- **3.** RIH w/ on/off tool on 2³/₄" workstring to 2,005'. RU cementer and circulated hole w/ 10 ppg brinewater. Latch onto and release RBP. POOH w/ RBP. RIH w/ on/off tool on 2³/₄" workstring to 4,470'. Latch onto and release RBP. POOH w/ RBP.
- 4. RIH w/ HM tbg-set CIBP on 2³/₄" workstring to 4,520'. RU cementer and set CIBP at 4,520'. Displace hole w/ ~70 bbls plugging mud, and pump 25 sx C cmt balanced plug 4,520 4,142' (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 378' in 4¹/₂" 11.6# casing).
- PUH w/ workstring to 2,919'. Load hole w/ plugging mud and pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 380' in 4½' 11.6# casing) balanced plug 2,919 2,541'. Base of Salt Plug
- PUH w/ workstring to 1,870'. Load hole w/ plugging mud and pump 25 sx C cmt w/ 2% CaCl₂ balanced plug 1,870 1,492' (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 378' in 4½" 11.6# casing). WOC & and tag this plug no lower than 1,770'. *Top of Salt Plug*
- PUH w/ workstring to 414'. ND BOP. NU wellhead. Load hole w/ plugging mud and circulate 30 sx C cmt (1.32 ft³/sk yield, 39.6 ft³ slurry volume, calculated fill 456' in 4½" 11.6# casing) to surface. Casing Shoe and Surface Plug
- 8. POOH w/ workstring. ND BOP. Wash up. RDMO location.
- **9.** Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company - Lower 48 - Mid-Continent BU / Permian Operations

