	State of New Mex	xico	Form C-103	
Office District I	Energy, Minerals and Natur	ral Resources	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240		1	WELL API NO.	
District II	OIL CONSERVATION	DIVISION	30-023-27300	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Fran	4	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE 🛛 FEE 🗌	
District IV	Santa Fe, NM 87	303	6. State Oil & Gas Lease No.	
1220 S St. Francis Dr., Santa Fe, NM			V-5490	
87505	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
	SALS TO DRILL OR TO DEEPEN OR PLU		7. Deade I talle of Olit rigidement I talle	
	CATION FOR PERMIT" (FORM C-101) FO		Carper McAlester ATE State	
PROPOSALS.)		<u> </u>	8. Well Number	
1. Type of Well: Oil Well	Gas Well Other	,	2	
2. Name of Operator		(9. OGRID Number	
Yates Petroleum Corporat	ion	-	025575	
3. Address of Operator	1011		10. Pool name or Wildcat	
105 S. 4 th Street, Artesia,	NM 88210		Eight Mile Draw; Abo	
	1111 00210		2.5	
4. Well Location	CCO C + C + d + NI - NI - d	1' 1 6	SO CARACTER FOR	
Unit Letter A:	660 feet from the North	line and 66	feet from the East line	
Section 25	Township 11S Ran	nge 34E 1	NMPM Lea County	
	11. Elevation (Show whether DR,			
	4142'	GR		
Pit or Below-grade Tank Application	or Closure 🗌			
Pit type Depth to Groundwat	er Distance from nearest fresh wa	iter well Distar	nce from nearest surface water	
			<u>į</u>	
Pit Liner Thickness: mi	Below-Grade Tank: Volume	DDIS; Cons	truction Material	
12. Check	Appropriate Box to Indicate Na	ature of Notice, R	eport or Other Data	
NOTICE OF IN	NTENTION TO:	SUBSI	EQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON 🔲	REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	.ING OPNS.□ P AND A □	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT .	JOB 🔲	
OTHER:	П	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
			give pertinent dates, including estimated date ch wellbore diagram of proposed completion	
of starting any proposed w				
of starting any proposed w				
of starting any proposed w				
of starting any proposed wo or recompletion. 10-31-07 to 11-16-07	ork). SEE RULE 1103. For Multipl	e Completions: Attac	ch wellbore diagram of proposed completion	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set	ork). SEE RULE 1103. For Multipl packer @ 5960'. Pressured tubing to	e Completions: Attac o 500#. Lost 250# in	ch wellbore diagram of proposed completion 2 mins. Moved RBP to 7000', set and	
of starting any proposed work recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M	ork). SEE RULE 1103. For Multipl packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min	ch wellbore diagram of proposed completion 2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal	
of starting any proposed work recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. M.	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested starting any proposed work and set to the starting and set t	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	ch wellbore diagram of proposed completion 2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal	
of starting any proposed work recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released and the starting of the starting any proposed work and the starting	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested starting any proposed work and set to the starting and set t	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released and the starting of the starting any proposed work and the starting	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 washed sand	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released and the starting of the starting any proposed work and the starting	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 washed sand	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released and the starting of the starting any proposed work and the starting	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Miqueeze hole to 500# for 15 mins, test	e Completions: Attac o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 s	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'.	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management to 500# for 15 mins, tested TOH.	o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 steed to 750# for 2 mins	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management of the set of th	o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 steed to 750# for 2 min sets of my knowledge a	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management of the set of th	o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 steed to 750# for 2 min sets of my knowledge a	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Misqueeze hole to 500# for 15 mins, tested TOH.	o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 steed to 750# for 2 min sets of my knowledge a	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and washed to 1000# for 2 mins 6 Washed sand with the company of th	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of the second	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Misqueeze hole to 500# for 15 mins, tested TOH.	e Completions: Attact o 500#. Lost 250# in d. Lost 400# in 2 min ixed and spotted 50 st ted to 750# for 2 min est of my knowledge a], a general permit or	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and washed to 1000# for 2 mins 6 Washed sand with the company of th	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of the second	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management of the for 15 mins, tested TOH. above is true and complete to the bear closed according to NMOCD guidelines.	e Completions: Attached to 500#. Lost 250# in d. Lost 400# in 2 minimaxed and spotted 50 steed to 750# for 2 minimaxed to 750# for 2 minimaxed and spotted to 750# for 2 minimaxed to 750#	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and washed to 1000# for 2 mins 6 Washed sand with the company of th	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management of the set of th	e Completions: Attached to 500#. Lost 250# in d. Lost 400# in 2 minimaxed and spotted 50 steed to 750# for 2 minimaxed to 750# for 2 minimaxed and sported by the complete of	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and attached) alternative OCD-approved plant in (attached) alternative OCD-approved plant in the community of the	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi D For State Use Only	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Manager hole to 500# for 15 mins, tested TOH. above is true and complete to the bear closed according to NMOCD guidelines TITLE Remain address:	e Completions: Attached to 500#. Lost 250# in d. Lost 400# in 2 minimaxed and spotted 50 steed to 750# for 2 minimaxed to 750# for 2 minimaxed and spotted to 750# for 2 minimaxed to 750#	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and attached) alternative OCD-approved plant in (attached) alternative OCD-approved plant in the community of the	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TC retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi D For State Use Only APPROVED BY:	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Management of the set of th	e Completions: Attached to 500#. Lost 250# in d. Lost 400# in 2 minimaxed and spotted 50 steed to 750# for 2 minimaxed to 750# for 2 minimaxed and sported by the complete of	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 Washed sand and attached) alternative OCD-approved plant in (attached) alternative OCD-approved plant in the community of the	
of starting any proposed wor recompletion. 10-31-07 to 11-16-07 MIRU PU. Set RBP @ 6360'. Set tested. Spotted 2 sx 20/40 sand. M 15% HCl. Released packer and TO retainer. Circulated clean. Tested soff RBP. Latched RBP, released an Set 2-7/8" tubing @ 9386'. I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi D For State Use Only	packer @ 5960'. Pressured tubing to oved packer to 6265'. Pressure teste H. Set cement retainer @ 6265'. Manager hole to 500# for 15 mins, tested TOH. above is true and complete to the bear closed according to NMOCD guidelines TITLE Remain address:	e Completions: Attached to 500#. Lost 250# in d. Lost 400# in 2 minimaxed and spotted 50 steed to 750# for 2 minimaxed to 750# for 2 minimaxed and sported by the complete of	2 mins. Moved RBP to 7000', set and ns. Moved packer to 6330'. Spotted 250 gal x Class "C" Neat. Drilled out cement and s, tested to 1000# for 2 mins 6 washed sand and attached) alternative OCD-approved plans an (attached) alternative OCD-approved plans of Element and attached alternative OCD-approved plans of Element and State of Sta	