Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OM B No 1004-0137
Expires: March 31, 200

` <u>.</u>	DELINATION OF THE INTERIOR					Expires: March 31, 2007		
BUREAU OF LAND MANAGEMENT					5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS					LC-065	5447		
Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name			
abandoned well. Use Form 3160 - 3 (APD) for such proposals.					N/A			

SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well					NM 85	5340		
Oil Well	Gas Well Other				9 Well No	ime and No.		
0.31		*				HOOTER 13 FED. #1		
2. Name of Operator RKI Explora	tion & Production, LLC				9. API W			
3a Address		3b. Phone N	In Grahida	mag anda)		3-31274		
3817 NW Expressway, Ste. 950	, Oklahoma City, OK 73112	405-949-		irea coaej		nd Pool, or Exploratory A	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
4. Location of Well (Footage, Sec., 2					10. Field at	tereor, or exploratory F E-REDGE; BONE SP	PINCS 58	
· -							idi (G)	
990' FNL & 1750' FEL 13-20S-33E NMPM					11. County or Parish, State			
Unit B					LEA C	COUNTY, NM		
	DDODDIATE DOVER TO	DIDICATE	MATURE	OF MOROE	DEDODE OF	0.000		
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE	NATURE	OF NOTICE,	REPORT, OF	ROTHER DATA		
TYPE OF SUBMISSION			TYPE	E OF ACTION			1	
	Acidize		****		·			
Notice of Intent	= :	Deepen			Start/Resume)	Water Shut-Off	•	
Notice of Intent	Alter Casing	Fracture T		Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Cons	struction	Recomplete	•	Other		
	Change Plans	Plug and A	Abandon	Temporarily	Abandon			
Final Abandonment Notice	Convert to Injection	✓ Plug Back		Water Dispos	al			
Attach the Bond under which th following completion of the invitesting has been completed. Fin determined that the site is ready 1. RIH AND SET A CAST 2. PERFORATE BONE SI 3. ACIDIZE AND FRACT RESIN-COATED PROPP. 4. CLEANOUT TO PBTD 5. INSTALL TUBING AND	etionally or recomplete horizontally to work will be performed or provided operations. If the operation is all Abandonment Notices must be for final inspection.) IRON BRIDGE PLUG @ 9,7 PRINGS FROM 9,404' TO 9,4 URE STIMULATE T W/ 1,00 ANT. @ 9,670'	y, give subsurfa de the Bond No results in a mul filed only after 700'. DUMP 137' AT 1-1/2 13 BBLS 30#	ace locations on file with tiple complete all requirement BAIL 30 LI SPF. & GEL WI	and measured and h BLM/BIA. Requition or recompletion ents, including reclinears, including reclinears.	true vertical depti uired subsequent r in in a new interva amation, have been on TOP OF CII	hs of all pertinent marker reports must be filed with al, a Form 3160-4 must be completed, and the open completed, and the open BP. AND 15,000#.16/30	s and zones. sin 30 days. e filed once erator has	
<i>O</i> CO	Need C-102	"Plat	" for	Teas	Bone S	prings	200	
14. I hereby certify that the foreg Name (Printed/Typed)	oing is true and correct		ı		•		_	
GENE SIMER	(PHONE 505-885-1313)		Title DD4	ADDICTION CU	DEDINTENDE	NT		
GENE SIVIER	(PHONE 505-885-1313) Title PRODUCTION SUI				TERMI LENDE	IAT	·····	

10/24/2007 Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

PATROLEUM ENGINEER Date

NOV 0 2 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.