10 30

Arrowhead Grayburg Unit #241 Convert to Injection

Page 2

Reference: Administrative Order #WFX-829

12/29/06 RIH w/pkr to 3,773'. Spot 1 bbl of acid. POOH to 3,678' & set pkr. Pmp 1,000 gals of 20% heated acid in three stgs w/10 bbl 9# spacer.

followed by gelled brine w/RS between stgs (lst stg – 500# of RS, 2nd

stg - 150# of RS).

1/3/07 Pmp 4,000 gals of 20% Hcl (perfs 3,676' to 3,770'). RU swab. Made 9

swab runs. Recovered 30 bbls of 100% water. Made 19 swab runs.

Recovered 64 bbls of 100% water.

1/5/07 Made 3 swab runs. Rec'd. 8 bbls of 100% water. RD swab.

1/6/07 RIH w/btm 5-1/2" pkr assembly. Set @ 3,672'. Change out rams to

2-3/8". PU & RIH w/on/off tool, 4 jts of rite-rap 2-3/8" 4.7#, J-55, EUE, 8rd tbg, top 5-1/2" pkr assembly, 109 jts of 2-3/8", 4.7#, J-55, EUE, 8rd, new IPC tbg. RIH 2'-2-3/8" IPC tbg sub latch onto btm pkr & set top pkr element @ 3,541'. Press up to 500 psig on tbg & pmp out plug. ND BOP & NU WH. RU chart. Press up to 500 psig

on TCA held for 30". Held ok.

1/9/07 RDMO PU. SI Well. Waiting on permit to CTI.

11/15/07 Rec'd. approved permit to Convert to Injection.

11/28/07 Converted well to Injection, original chart was sent in February, 07'.

Copy of chart is attached.

Reference: Administrative Order #WFX-829 Attached

The EMERCY Arrange of the State of the State