State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		101300 5 27 2001
<u>DISTRICT I</u> 1625 N. French Dr., Hobbs, NM 88240	1220 South	St. Francis Dr.	WELL API NO 30-025-28942	
<u>DISTRICT II</u>		NM 87505	5. Indicate Type of Lease	<i></i>
1301 W Grand Ave, Artesia, NM 88210		10 1 1553	STATE	FEE 🕏
DISTRICT III			6. State Oil & Gas Lease No	· ·
1000 Rio Brazos Rd, Aztec, NM 87410	/	Nr.	3\	
E .	OTICES AND REPORTS ON WE	4 1/3 -	7 Lease Name or Unit Agre	ement Name
	ROPOSALS TO DRILL OR TO DEEPEN APPLICATION FOR PERMIT" (Form Ç		North Hobbs (G/SA) Ur Section 30	iit /
Type of Well. Oil Well	Gas Well Other It	niector.	8 Well No. 233	
2 Name of Operator		35-12346	9. OGRID No. 157984	/
Occidental Permian Ltd. 3. Address of Operator			10 Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, T2	X 79323		10 Toor hame of Whacat	110003 (G/3A)
4. Well Location	17525			
Unit Letter K : 2455	Feet From The South	Fee	et From The West	Line
Section 30	Township 18-S	Range 38-I	E NMPM	Lea County
	11. Elevation (Show whether DF, R 3666' KB	KB, RT GR, etc.)		
Dit an Dalam and Taul Application				
Pit or Below-grade Tank Application	or Closure	. C. J	D'-1	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	iterial	
12. Chec	ck Appropriate Box to Indicate N	ature of Notice, Report, or 0	Other Data	
NOTICE OF IN			SEQUENT REPORT	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERII	NG CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS PLUG 8	ABANDONMENT
	=	CASING TEST AND CEMEN		
PULL OR ALTER CASING	Multiple Completion		41.10B	
OTHER: Squeeze/Run partial line	er/perf/AT X	OTHER		
 Describe Proposed or Completed O proposed work) SEE RULE 1103 Kill well. POOH w/injection equitable. Clean out well to 4295'. RIH w/CICR set @4060'. Squeez Drill out cement & retainer to PB'. RIH w/FJ liner. Clean out to PBTD. Perforate hole. Acid treat well. Perform scale squeeze. Run back in hole w/injection equitable. Test casing & chart for the NMC 	i. For Multiple Completions: Attach ipment. ze perfs. TD @4338'.			
I hereby certify that the information above is	s true and complete to the best of my know	wledge and belief I further certify	that any pit or below-grade tan	k has been/will be
constructed or closed according to NMOCD guideline	, a general permit	or an (attached) alternativ	e OCD-approved	
SIGNATURE Mendy	, ti Johnon	TITLE Administrative	Associate DA	TE 12/19/2007
TYPE OR PRINT NAME Mendy (A.	Johnson () E-mail address:	mendy_johnson@oxy.com	TELEPHONE N	O. 806-592-6280
For State Use Only	DI June OCHELI	REPRESENTATIVE WAST		EEB 0 6 2008
APPROVED BY APPROVALUE OF APPR	-,0-,1-1	TITLE	D	ATE
CONDITIONS OF APPROVAL IF ANY.				