Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-HOBBS

FORM APPROVED OMB NO. 1004-0135 Expires November 30, 2000

5. Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6 If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.				,	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7 If Unit or CA/Agreement, Name and/or	
1 Type of Well X Oil Well Gas Well Other				8 Well Name and No.	
2. Name of Operator			/	o won want	#127 —
OXY USA WTP Limited Partnership 3a Address [3]		3b. Phone No (include a	192463 9 API Well No		
P.O. Box 50250, Midland, TX 79710-0250		432-685-5717	,	30 - 025 - 060 10 Field and I	Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FNL 510 FWL NWNW(D) 12-20S-37E				Eumont Yat	es 7Rvr Qn
000 FRE 310 FWE NWNW(D) 12-203-37	C			11. County or	Parish, State
				Lea	NM
12. CHECK APPROPRIATE	BOX(ES) TO INC	ICATE NATURE OF	NOTICE, REPO	ORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	X Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	n ,	Well Integrity
	Casing Repair	New Construction	Recomplete	;	X Other Perforate
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily	/ Abandon	Add'l Interval
	Convert to Injectio	n Plug Back	Water Dispo	osal	
If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment Metermined that the final site is ready for final inspection of the involved operations. TD-3850' PBTD-3585' Perfs. 1. RUPU, NUBOP. TIH w/ bit & DC's 2. Set CIBP on wire line @ 3600'. 3. Spot acid across pay interval. perforate following depths wit Gun at 2714, 2716, 2746, 2748, 3132, 3134, 3142, 3145, 3157, 3546, 3554, 3558, 3560. 4. Run work string with Hook-wall 5. Acid-Frac all perfs with 13000 pumped. Swab test the well. 6. POH w/ work string and Pkr. Ru	romed or provide the B fithe operation results in Notices shall be filed onlection) -3690-3807' on 2-7/8" tbg. Correlate to W h 2SPF using Hal 2760, 2794, 280 3253, 3278, 329 Pkr. Set Pkr @ gals 15% NE Fe un tbg & Pkr. Se	ond No. on file with BLM/a multiple completion or my after all requirements, in CIBP-3585' DO CIBP @ 3585' & destern Gammatron Fliburton 4" thru-07, 2972, 2985, 2980, 3309, 3316, 3350, 2650'. Pressure but the state of the sta	POH. Radioactive L csg Port Pluc 39, 2999, 300 59, 3364, 337 backside to 5 Drop 40 bal Swab and INE BY APR	JAN JAN JAN JAN Og dated s9 Millienniu 77, 3387, 3 77, 3387, 3 flow back A 2008	ashall be filed within 30 day m 316074 shall be filed once mplered and the operator have 2 5 2008 2 5 2008 2 5 2008 2 5 2008 3 102, 3112, 437, 3539 after 10000 gal to tank. OR A FLAN
14 Thereby certify that the foregoing is true and correct	a _k	Title			
Name <i>(Printed/Typed)</i> David Stewart		İ	gulatory Anal	lyst	
li Ster		Date 146			10.00
THIS	SPACE FOR FEDE	RAL OR STATE OFF			
Approved by	OC DISTRI	CT SUPPRISOR/GE	MERAL MANA	GER Date	EED O a soon
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to the which would entitle the applicant to conduct operations the	hose rights in the subject	rant or Office ot lease			FEB 0 6 2008