## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OI	L CONSERV	ATION DIVISIO	ON		,	,	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88	8240		St. Francis Dr. NM 87505	WEI	LL API NO. 30-025-07445	5 /		
DISTRICT II		Suitu 1 0,	1111 07505	5. Ir	idicate Type of Lease	e ,		
1301 W. Grand Ave, Artesia, NM 88210					STATE	$\overline{X}$ $F$	FEE	
DISTRICT III				6. S	tate Oil & Gas Lease	No.		
1000 Rio Brazos Rd, Aztec, NM 87-	410							
SUNDRY NOTICES AND REPORTS ON WELLS					ease Name or Unit A	greement Nan	ne	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)					th Hobbs (G/SA) tion 29	Unit		
1. Type of Well: Oil Well	X Gas Well	Other		8. W	Vell No. 341		/	
Name of Operator     Occidental Permian Ltd.	· •			9.0	GRID No. 1579	84		
3. Address of Operator				10.	Pool name or Wildca	t Hobi	bs (G/SA)	
HCR 1 Box 90 Denver	City, TX 79323							
4. Well Location								
Unit Letter O	Feet From The	e South	2318	Feet From	The East	Line		
Section 29	Towns		Range	38-E	NMPM	Lea	a County	,,,,,,
	3643' GL	(Show whether DF, R	KB, RI GR, etc.)					
Pit or Below-grade Tank Applic	ation or Clos	ure					4 20	1000
Pit Type Depth o	f Ground Water	Distance from 1	earest fresh water well_		Distance from near	est surface w	ater	
Pit Liner Thickness	_ mil Below-Grade 7	Γank: Volume <u>· .</u>	bbls; Construction	on Material	*	-		
12."			ture of Notice, Repor					
NOTICE C	OF INTENTION TO:	<u> </u>		SUBSEQU	JENT REPOR	ΓOF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK					. ALTE	RING CASIN	ig [	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN					PLUC	G & ABANDO	NMENT [	
PULL OR ALTER CASING	Multiple Compl	letion	CASING TEST AND C	EMENT JOB	. 🗀		,	
OTHER: Squeeze perfs to s	hut off gas	Х	OTHER				Γ	
<ol> <li>Describe Proposed or Comple proposed work) SEE RUL.</li> <li>RU &amp; kill well.</li> <li>Cleanout to PBTD @4202'</li> <li>Plug back. Set CICR @3974.</li> <li>Squeeze perfs.</li> <li>Perforate well.</li> </ol>	E 1103. For Multiple Cor	state all pertinent d mpletions: Attach v	vellbore diagram of prop	oosed comple	ding estimated date tion or recompleted	on.	iny	
6. Acid treat w/2500 gal of 15	% NEFE HCI acid.		<b>S</b>	a com Ph		<b>A</b>		
7. Perform scale squeeze.					_		1	
9. Return well to production.				JAN :	2 5 2008			
				OBE	BS OC	D		
I hereby certify that the information a	above is true and complete t	o the best of my know	ledge and belief. I further of	certify that any	pit or below-grade t	ank has been/v	will be	
constructed or			_		·			- 3
closed according to NMOCD gui	, a gen	neral permit	or an (attached) alter	rnative OCD	-approved		;-	
SIGNATURE   New	dy UY	Phnow	TITLE Administr	ative Associ	iate I	DATE <u>01</u> /	/24/2008	,
TYPE OR PRINT NAME Men	dy A Johnson	E-mail address:	mendy_johnson@oxy	y.com	TELEPHONE	NO. 806-	-592-6280	4
For State Use Only	4.0:	ing sells then a directions of attenti	· Prof. Charleston & San San San San San Care.	IRTHA LAKE	NACED	FEB (	0 6 2008	'
APPROVED BY	William	OC DISTRICT	SUPPLYSONGEN	acether bara	WHOLK	DATE	- O FAAA	;'
CONDITIONS OF APPROVAL IF A	aNY:							11