Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD-HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

5. Lease Serial No.


SUNDRY NOTICES AND REPORTS ON WELLS

NMLC031740B

abandoned well. Use Form 3160-3 (APD) for such proposals.			0. II III	o. If fidding Allottee of Tibe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Ui	nit or CA/Agreement, Name and/or N 48A	
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator				Name and No. e Monument Unit 260	
XTO Energy Inc.			9. API	Well No.	
 3a. Address 200 N. Loraine, Ste. 800 Midland, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit W; 330 feet from the South line & 2310 feet Section 4; Township: 21S; Range 36E 		b. Phone No. (include an n the East line.	10. Fie Eunic n And	5-04463 Eld and Pool, or Exploratory Area e Monument, Grayburg-Sa res ounty or Parish, State	
Section 1, 10mining. 213, Runge 302	•		Lea	NM	
12. CHECK APPROPRIATE	BOX(ES) TO INDIC	ATE NATURE OF I			
TYPE OF SUBMISSION		TYI	PE OF ACTION		
Notice of Intent X Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Start/Res Reclamation Recomplete	water Shut-Off Well Integrity Other Acid	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal	Stimulation	
If the proposal is to deepen directionally or recompattach the Bond under which the work will be per following completion of the involved operations. It testing has been completed. Final Abandonment Metermined that the final site is ready for final inspect 8/25/07 MIRU PU. POOH w/ rods. To also while circ. Hammer on 12 brine while circ. Hammered OH w/3, btm w/30 BW. Dropped ball to sheat Made 19 swab runs in 3-1/5 hrs. 8/29/07 RU pmp trk to tbg. Loaded	formed or provide the Bor of the operation results in a Notices shall be filed only action.) agged btm (3,877') 5 jts of 2-7/8" J-200 gals of 20% 90 r sleeve in tool. Rec 100 BW & 0 BO.	od No. on file with BLM/multiple completion or reinter all requirements, inc. 55 tbg. Washed CO/10 HCL (approx BLWTR 115. Avg 3 EFL @ 2,500 FF	BIA. Required subsequent completion in a new intervaluding reclamation, have but the fir 3,704' - 3,8 30 bbls per stand 5.5 BPM. Avg. equi	t reports shall be filed within 30 day ral, a Form 3160-4 shall be filed onceen completed, and the operator has 77' w/100 bbls of 9# 1). Flushed acid to p. BFL @ 1.350' FFS.	
	RECEIV	•	ACCEPTE	D FOR RECORD	
A	JAN 2 3 200		JA	N 2 1 2008	
	HOBBS (CD	DYDER'U O	T LAND MANAGEMENT	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Sherry Pack		T _{itle} Regulat		F LAND MANAGEMENT BAD FIELD OFFICE	
Sherry tack		Date 01/08/20			
U THIS	SPACE FOR FEDER	AL OR STATE OFF	ICE USE		
Approved by Chris Williams		UPERWISCRAGOS	rai mynacht	Date FEB 0 7 2008	
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the	those rights in the subject	nt or Office lease			



WELL DATA SHEET



RU Bo Monk tbg tstrs. Press tetd 2-7/8" tbg to 5,000 psig below the slips. PU 6 RIH w/BPMA, PS, 2.5" x 2-3/4" x 24' THE pmp w/3' plngr (SN# EMSU1010), 7 jts 2-7/8", 6.5#, J-55, EUE, 8rd tbg, 5-1/2" TAC & 112 jts 2-7/8", 6.5#, J-55, EUE, 8rd tbg. RD Eo Monk. ND BCP. Set TAC w/18 pts tens. NU WH. RIH w/1" on/off tool, 39-1" D-90 rods, 99-3/4" D-90 rods, 11-1" D-90 rods, 3-1" D-90 pony rods (6', 4' & 8') & 1-1/2" x 26' SM PR. Latched onto pmp. SWO & HWC. RU Key pmp trk. Loaded tbg w/15 BW. Press tbg to 500 psig in 1 stroke, held CK. RE pmp trk. RDMC PU. RWTP. (Mandrel in TAC was found split @ Garner shop).