		()
02-06-08;10:Ó1AM;	0 0	;9407238113 # /8/ 11
	Mrs. o	
- (M) 1 000 1 00	Nill Mile	
	Sir Sir	
Submit 2 Copies To Appropriate District State of	of New Mexico	Form.C-103
	ls and Natural Resources	October 25, 2007
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-05/82
130) W. Grand Ave., Artesia, NM 88210 UIL CONSEL	RVATION DIVISION ath St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa	Fe, NM 87505	STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	•	
SUNDRY NOTICES AND REPORTS	ON WELLS	7. Lease Name or Unit Agreement Name Drata North Wolfzags
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DI DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO	ORM C-101) FOR SUCH	Aser # 57100 57370
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Al Other	Injection well	8. Well Number
2 Name of Operator	Company	9. OGRID Number 01995-8
3. Address of Operator		10. Pool name or Wildcat
	FE/15 Tx 76307	Dester Wolliams
4. Well Location Unit Letter \(\text{! 1580 feet from the } \) line and \(\frac{290}{20} \) feet from the \(\text{\text{!}} \) line		
Section 3.5 Township/4.5 Range 32 NMPM County Lra		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 7825 KB		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDO	ON REMEDIAL WOR	RILLING OPNS. P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMEN	
OTHER:	☐ M Location is	ready for OCD inspection after P&A
All pits have been remodiated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. X A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
Anchors, tead then, he downs and rises in the beat state of the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. \ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from		
non-retrieved flow lines and pipelines.		
ust an all week have groundeted return this form to the appropriate District office to schedule an inspection. If more than one		
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed. SIGNATURE DATE 2-6-08 TYPE OR PRINT NAME Sob 6: Lover E-MAIL: Bollower & Sou Met PHONE: 500-723-2/66		
SIGNATURE LA LINE	TITLE Engier	DATE 2-6-08
TYPE OR DELICE MANY R. L. C. L.	E-MAIL: R. Lame (2)	Ster 14 PHONE: 540-723-2166
For State Use Only		
•	TITLE	DATE
APPROVED BY: Conditions of Approval (if any):		