	NITED STATES IENT OF THE INTERIC			FORM APPROVED OMB NO. 1004-0135 Exputes: November 30, 2000	
BUREAU O	F LAND MANAGEME	NT OCD-HOL	000	Expires: November 30, 2000 5 Lease Serial No.	
SUNDRY NOTIC	ES AND REPORTS	ON WELLS	9 D 39	891038170 - NM27722	
Do not use this form abandoned well. Use	n for proposals to drill c Form 3160-3 (APD) fo	or to re-enter an or such proposals.		6. If Indian, Allottee or Tribe Name	
				# 19.2463	
1 Type of Well		7. If Unit or CA/Agreement, Name and/or N Myers Langlie Mattix Unit			
X Oil Well Gas Well Other A Name of Operator				8 Well Name and No 188	
OXY USA WTP Limited Partnership		192463			
3a Address		3b. Phone No. (include area	a code)	9. API Well No 30-025-25990	
P.O. Box 50250, Midland, TX 797		432-685-5717		10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R, M., or Sur				Langlie Mattix 7Rvr Qn-GB	
660 FSL 660 FEL SESE(P) Sec 3	T24S R37E 1				
				11. County or Parish, State	
12. CHECK APPROPRIA	ATE BOY(ES) TO IN	DICATE NATURE OF N			
TYPE OF SUBMISSION					
			E OF ACTION		
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamatio	n Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		
Errol Abandonment Nation	Change Plans	X Plug and Abandon	Temporarily		
Final Abandonment Notice	Convert to Inject		Water Disp	<u>Approved</u> 9/5/0/	
Fituen the bond under which the work will b	e performed or provide the	Bond No. on file with BLM/BI	IA Required su	posed work and approximate duration thereof ical depths of all pertinent markers and zones bsequent reports shall be filed within 30 days	
following completion of the involved operatio testing has been completed. Final Abandonm determined that the final site is ready for final	e performed or provide the ns. If the operation results tent Notices shall be filed o	Bond No. on file with BLM/Bl in a multiple completion or reco only after all requirements, inclu	IA. Required su ompletion in a neurophyloxic in	ical depths of all pertinent markers and zones bsequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has	
 following completion of the involved operation testing has been completed. Final Abandonm determined that the final site is ready for final TD-3747' PBTD-3430' Pe 8-5/8" 24# csg @ 507' w/400sx, 5-1/2" 15.5# csg @ 3746' w/800 1. RIH & Tag CIBP & Cmt @ 3430 2. M&P 25sx cmt @ 2500-2400' 3. M&P 25sx cmt @ 1150-1050' W 4. M&P 25sx cmt @ 150'-1050' W 4. M&P 25sx cmt @ 150' Surface 10# MLF between plugs 	e performed or provide the ms. If the operation results lent Notices shall be filed o inspection.) erfs-3504-3602' 12-1/4" hole, TOC sx, 7-7/8" hole, T ' M&P 25sx cmt to OC-Tag -Tag	Bond No. on file with BLM/BI in a multiple completion or reco only after all requirements, inch CIBP-3450' C-Surf-Circ TOC-Surf-Circ 3330' CONTRACTIONS SEE ANTIAONS SEE ANTIAONS	IA. Required su ompletion in a n uding reclamatio	ical depths of all pertinent markers and zones bequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has RECEIVED FEB 2 8 2008 JOBBS OCD	
 following completion of the involved operation testing has been completed. Final Abandonum determined that the final site is ready for final TD-3747' PBTD-3430' Pe 8-5/8" 24# csg @ 507' w/400sx, 5-1/2" 15.5# csg @ 3746' w/800 1. RIH & Tag CIBP & Cmt @ 3430 2. M&P 25sx cmt @ 2500-2400' 3. M&P 25sx cmt @ 1150-1050' W 4. M&P 25sx cmt @ 557-457' WOC 5. M&P 25sx cmt @ 150' -Surface 10# MLF between plugs 	e performed or provide the ms. If the operation results lent Notices shall be filed o inspection.) erfs-3504-3602' 12-1/4" hole, TOC sx, 7-7/8" hole, T ' M&P 25sx cmt to OC-Tag -Tag	Bond No. on file with BLM/BI in a multiple completion or reco only after all requirements, inch CIBP-3450' C-Surf-Circ TOC-Surf-Circ 3330' CONTRACTIONS SEE ATTAONS SEE ATTAONS Title Title	IA. Required su ompletion in a n- uding reclamatio	ical depths of all pertinent markers and zones bequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has RECEIVED FEB 2 8 2008 10BBS OCD	
 following completion of the involved operation testing has been completed. Final Abandonm determined that the final site is ready for final TD-3747' PBTD-3430' Pe 8-5/8" 24# csg @ 507' w/400sx, 5-1/2" 15.5# csg @ 3746' w/800 1. RIH & Tag CIBP & Cmt @ 3430 2. M&P 25sx cmt @ 2500-2400' 3. M&P 25sx cmt @ 1150-1050' W 4. M&P 25sx cmt @ 150'-1050' W 4. M&P 25sx cmt @ 150' Surface 10# MLF between plugs 	e performed or provide the ms. If the operation results lent Notices shall be filed o inspection.) erfs-3504-3602' 12-1/4" hole, TOC sx, 7-7/8" hole, T ' M&P 25sx cmt to OC-Tag -Tag	Bond No. on file with BLM/BI in a multiple completion or reco only after all requirements, inch CIBP-3450' C-Surf-Circ TOC-Surf-Circ 3330' CONTRACTIONS SEE ATTAONS SEE ATTAONS Title Title	IA. Required su ompletion in a n uding reclamatio	ical depths of all pertinent markers and zones bequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has RECEIVED FEB 2 8 2008 FEB 2 8 2008	

Conditions of approval, if any, are affached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those nights in the subject lease which would entitle the applicant to conduct operations thereon δ

.

Title 18 U S C. Section 1001, and Title 43 U S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

WEŚLEY W. INGRAM

Myers Langlie Mattix Unit #188 OXY USA WTP Limited Partnership February 26, 2008 Plug and Abandon Conditions of Approval

- 1. Ok
- 2. Plug to be set from 2530-2375', minimum 25 sacks. WOC 4 hours. Plug to be tagged at 2375' or shallower.
- 3. Plug to be set from 1186-1076', minimum 25 sacks. WOC 4 hours. Plug to be tagged at 1076' or shallower.

4. Ok

5. Ok

6. Cut casing, install dry hole marker and clean location.

WWI 022608

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2: <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3 <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.



UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT Carlsbad Field Office** 620 E. Greene St. Carlsbad, NM 88220

Interim Reclamation Procedures for Permanently Abandoned Federal Wells

1. After Subsequent Report of Abandonment, Form 3160-5, is filed and approved by the BLM the surface protection specialist (SPS) will conduct a surface inspection of the abandonment. The SPS will establish the reclamation requirements the operator will need to complete. DO NOT START RECLAMATION UNTIL THE SPS HAS **INSPECTED THE LOCATION.**

2. The reclamation requirements will be given to an environmental protection specialist (EPS). The EPS will issue the operator a Notice of Written Order outlining the reclamation requirements. DO NOT START **RECLAMATION UNTIL A NOTICE OF WRITTEN ORDER FOR RECLAMATION HAS BEEN** RECEIVED. The EPS will be responsible for all further abandonment work and inspections.

3. Notification: CONTACT THE EPS 3 DAYS PRIOR TO RECLAMATION WORK. This notification gives the EPS an opportunity to discuss by phone or on location the reclamation requirements, any special concerns and the timeframes. It also allows the EPS an opportunity to witness various aspects of the reclamation work to determine if an adequate seedbed has been prepared and all reclamation requirements have been completed. CONTACT THE EPS AT LEAST 3 DAYS PRIOR TO SEEDING. This allows the EPS to witness the seeding operation to make sure the location is seeded properly and with the appropriate seed mixture, DO NOT START **RECLAMATION UNTIL THE EPS HAS BEEN NOTIFIED.** 1. an at the constants - -

4. After reclamation work has been completed, submit the I & E copy of the Notice of Written Order to the BLM. sector of the signed by a company representative and dated. Also submit one original and five copies of the sector Final Abandonment Notice, Form 3160-5. The report should state that all reclamation work has been completed, and the state of the state 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 -and the location is ready for a final abandonment inspection.

. ... See 12 5 <u>5</u> 7 - 5 5. The BLM will continue to monitor the location to ensure the location vegetates successfully, and salts from the reserve pit do not leach to the surface. The location will be monitored until such time as vegetation (20%) is - 5 established evenly across the location (including the reserve pit and access road). Once EPS determines that vegetation (20%) is evenly spread across the location, final abandonment will be authorized.

If there are any questions please feel free to contact any of the following:

Jim Amos Supervisory Environmental Protection Specialist (575) 234-5909

.

Barry Hunt Surface Protection Specialist (575) 234-5965

Todd Suter Surface Protection Specialist (575) 234-5987

Trishia Bad Bear Natural Resource Specialist - Lea County (575) 393-3612

Cody Layton Natural Resource Specialist (575) 234-5959

Paul Evans **Environmental Protection Specialist** (575) 234-5977

.

Terry Gregston **Environmental Protection Specialist** (575) 234-5958

10/18/2006

Form 3160-5					
(August 1999)		TED STATES	_		FORM APPROVED
		T OF THE INTERIO		OBBC	OMB NO. 1004-0135 Expires: November 30, 2000
		AND MANAGEME			5 Lease Senal No
	SUNDRY NOTICES	AND REPORTS	ON WELLS		891038170 - NM27722
	Do not use this form for	r proposals to drill o	r to re-enter an		6. If Indian, Allottee or Tribe Name
	abandoned well. Use Fo	rm 3160-3 (APD) fo	r such proposals.		
	SUBMIT IN TRIPLICATE	Other instruction	s on reverse side		7. If Unit or CA/Agreement, Name : Myers Langlie Mattix Uni
	Gas Well Other	•			8. Well Name and No.
2. Name of Operator OXY USA WTP L	imited Partnership		1924	63	-188
3a Address			3b Phone No. (include		9. API Well No.
<u> </u>	50. Midland, TX 79710	- 0250	432-685-5717		<u>30-025-25990</u>
	ootage, Sec., T, R, M., or Survey				10 Field and Pool, or Exploratory A Langlie Mattix 7Rvr Qn-G
660 FSL 660 F	EL SESE(P) Sec 3 T24	4S R37E			
					11. County or Parish, State
12.	CHECK APPROPRIATE	BOX(ES) TO INE			ORT OR OTHER DATA
TYPE C	OF SUBMISSION			YPE OF ACTION	ONT, ON OTHER DATA
X Note	ce of Intent				
	Intent		Deepen	Production	(Start/Resume) Water Shut-Off
Subs	sequent Report	Alter Casing	Fracture Treat	Reclamatio	on Well Integrity
		Casing Repair	New Construction	Recomplet	e Other
Final	Abandonment Notice	Change Plans	X Plug and Abandon	Temporaril	
		Convert to Injectio	on Plug Back	Water Disp	
Attach the Bond following comple testing has been determined that t	under which the work will be per etion of the involved operations. I completed. Final Abandonment N he final site is ready for final inspe	formed or provide the B f the operation results in Notices shall be filed on ection.)	lond No. on file with BLN	I/BIA. Required su recompletion in a n including reclamatio	pposed work and approximate duration to tacal depths of all pertinent markers and ubsequent reports shall be filed within 3 ew interval, a Form 3160-4 shall be file on, have been completed, and the operat
Attach the Bond following complete testing has been - determined that to TD-3747* 8-5/8" 24# 0 5-1/2" 15.5 1. RIH & Tag 2. M&P 25sx 3. M&P 25sx 4. M&P 25sx 5. M&P 25sx	under which the work will be per etion of the involved operations. I completed. Final Abandonment N he final site is ready for final inspe	formed or provide the B f the operation results in Notices shall be filed on ection.) - 3504-3602 - 1/4" hole, TOC- 7-7/8" hole, TOC &P 25sx cmt to 3	ond No. on file with BLM a multiple completion or by after all requirements, i CIBP-3450' Surf-Circ C-Surf-Circ	I/BIA. Required su recompletion in a n including reclamatio	used depins of all pertinent markers and used used within 3
Attach the Bond following complete testing has been - determined that if TD-3747' 8-5/8" 24# 0 5-1/2" 15.5# 1. RIH & Tag 2. M&P 25sx 3. M&P 25sx 3. M&P 25sx 4. M&P 25sx 5. M&P 25sx 10# MLF	under which the work will be per etion of the involved operations. I completed. Final Abandonment N the final site is ready for final inspe PBTD-3430' Perfs csg @ 507' w/400sx, 12 # csg @ 3746' w/800sx, g CIBP & Cmt @ 3430' Mi cmt @ 2500-2400' cmt @ 1400-1000' WOC- cmt @ 150'-2400' cmt @ 150'-Surface between plugs the foregoing is true and correct d) wart 	formed or provide the B f the operation results in Notices shall be filed on ection.) - 3504-3602' - 1/4" hole, TOC- 7-7/8" hole, TOC- 7-7/8" hole, TOC &P 25sx cmt to 3 Tag 1150 - 1050' SPACE FOR FEDE	In a multiple completion or by after all requirements, in CIBP-3450' Surf-Circ C-Surf-Circ 330' Title Date RAL OR STATE OFF Title	BIA. Required sur recompletion in a n neluding reclamation	yst
Attach the Bond following complete testing has been determined that if TD-3747' 8-5/8" 24# 0 5-1/2" 15.5 1. RIH & Tag 2. M&P 25sx 3. M&P 25sx 3. M&P 25sx 4. M&P 25sx 5. M&P 25sx 5. M&P 25sx 10# MLF	under which the work will be per etion of the involved operations. I completed. Final Abandonment N the final site is ready for final inspec- PBTD-3430' Perfs csg @ 507' w/400sx, 12 # csg @ 3746' w/800sx, 12 methods a state of the state of	formed or provide the E f the operation results in Notices shall be filed on ection.) - 3504-3602' - 1/4" hole, TOC- 7-7/8" hole, TOC- 7-7/8" hole, TOC &P 25sx cmt to 3 Tag 1150 - 1050' SPACE FOR FEDE this notice does not wan tose rights in the subject reon	Title Ti	UBA. Required sur recompletion in a n neluding reclamation	vst

OXY USA WTP LP Myers Langlie Mattix Unit #188 API No. 30-025-25990

25sx @ 150'-Surface

25sx @ 557-457' WOC-Tag

1150-1050 25sx @ 1400-1000' WOC-Tag

25sx @ 2500-2400'

25sx @ 3430-3330' 6/06-CIBP @ 3450' w/ 2sx



· . · .

~

12-1/4" hole @ 507' 8-5/8" csg @ 507' w/400sx-TOC-Surf-Circ

7-7/8" hole @ 3747' 5-1/2" csg @ 3746' w/800sx-TOC-Surf-Circ

Perfs @ 3504-3602'

SUNDRY NOTICE SPECIAL STIPULATIONS

1. Approval is granted to plug this well with the following modifications to the proposed plugging procedure.

)

2. The plug proposed for 1100' should be moved to 1150' for the Top of the Salt.

All plugs below the surface plug must be at least 25 sacks of cement and 100' plus an additional 10% for each 1000 feet of depth.

<u>Plugging procedures must conform to 43 CFR 3162.6.d and Onshore Order No.</u> 2.III.G or NMOCD orders if they are more stringent.

ALL OF THE WORK AUTHORIZED HERE MUST BE COMPLETED WITHIN 90 DAYS.

<u>Engineering</u> <u>can be reached at 505-706-2779 for any variances that might be necessary.</u>

F Wright 9/5/07

و السراد و