State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSER'	VATION DIVISIO	\mathbf{N}				
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505			WELL API NO. 30-025-34870			
DISTRICT II		,	5 Indicat	e Type of Lease			
1301 W. Grand Ave, Artesia, NM 88210				STATE X FEE			
DISTRICT III				6 State Oil & Gas Lease No.			
1000 Rio Brazos Rd, Aztec, NM 87410						1	
SUNDRY NOTICES AND REPORTS ON WELLS				7 Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North H	North Hobbs (G/SA) Unit			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)				Section 29			
1. Type of Well. Oil Well X Gas Well Other				8. Well No. 624			
2. Name of Operator				9. OGRID No. 157984 /			
Occidental Permian Ltd. 3. Address of Operator				name or Wildcat	Hobbs (G/SA)		
HCR 1 Box 90 Denver City, TX 79323				iame or macar	110003 (G/3A)		
4. Well Location							
Unit Letter N : 1150	Feet From The South	1948	Feet From The	West	Line		
Section 29	Township 18-S	Range	38-E	NMPM	Lea County	,	
	11. Elevation (Show whether DF, 3641' GL	RKB, RT GR, etc.)					
Put or Palous grade Tank Application	Clasura C						
Pit or Below-grade Tank Application	or Closure					İ	
Pit Type Depth of Ground				ice from nearest su	irface water		
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction	n Material				
	ck Appropriate Box to Indicate N				- .		
NOTICE OF IN	TENTION TO:	5	OBSEQUEN	T REPORT OI —	r:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING	CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN				PLUG & A	BANDONMENT		
PULL OR ALTER CASING	JLL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN						
OTHER: Open additional perfs/acid stimulate X OTHER:				····················			
13. Describe Proposed or Completed O proposed work) SEE RULE 1103	perations (Clearly state all pertinent For Multiple Completions: Attach				tarting any		
1. Kill well. POOH w/ESP equipme	nt.						
2. Clean out to PBTD @4340'. 3. Perforate well @4055-64'. 4. A sidewater Plant (40 bbl of 150) UCL DAD side							
3. Perforate well @4055-64'.4. Acid treat well w/40 bbl of 15% HCL PAD aicd.							
5. Pump scale squeeze.	ica i i ia dicai						
6. Run back in hole w/ESP equipment.				FEB 1 5 2008			
7. Return well to production.					AND TIME		
			HOE	385 O	CD		
			5 6 CES	P COLUMN TO THE	-		
I hereby certify that the information above is	strue and complete to the best of my kno	owledge and belief. I further c	ertify that any pit of	or below-grade tank h	as been/will be		
constructed or closed according to NMOCD guidelines	s , a general permit	or an (attached) alter	native OCD-app	roved			
~ ·		plan	PP				
SIGNATURE Mende	of Caronnon	TITLE Administra	ative Associate	DATE	02/12/2008		
TYPE OR PRINT NAME Mendy A	onnson E-mail address:	mendy_johnson@oxy	.com	TELEPHONE NO.	806-592-6280		
For State Use Only	112 3	Mariana di America	_				
APPROVED BY	Ollian OCDS	TRUCTURE PERVISOR	GENERAL MA	MAGER DAT	E MAR 06	2000	

CONDITIONS OF APPROVAL IF ANY: