
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION	Kenba 2 2 200
DISTRICT I	1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr. , Hobbs, NM 88240	Santa Fe, NM 87505	30-025-26934
DISTRICT II		5 Indicate Type of Lease STATE X FEE
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III		6 State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		o state on ee das bease no.
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
1	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit —
	PPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 29
Type of Well: Oil Well	Gas Well Other Injector	8. Well No. 222
2. Name of Operator	Gas were Guer Injector	9. OGRID No. 157984
Occidental Permian Ltd.		
3. Address of Operator	70222	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 4. Well Location	19323	
Unit Letter F: 1370	Feet From The North 1850 F	eet From The West Line
Section 29	, , , , , , , , , , , , , , , , , , ,	-E NMPM Lea County
Section 29	Township 18-S Range 38 11. Elevation (Show whether DF, RKB, RT GR, etc.)	-E NAME Lea County
	3643' GL	
Pit or Below-grade Tank Application	or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING O	PNS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEME	ENT JOB
OTHER:	OTHER: High casing p	oressure X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
 RUPU & RU. Kill well. Set blanking plug in profile @4127'. Test tubing & casing. OK. POOH w/blanking plug. 		
3. ND wellhead. POOH w/tubing & packer,		
 4. RIH w/redressed Arrowset 1-X packer on 129 jts of 2-7/8" Duoline tubing. Packer set @4126' 5. Hydro test 2-7/8" tubing in hole to 500 PSI. 		
 5. Hydro test 2-7/8" tubing in hole to 500 PSI. 6. Test casing to 600# for 30 minutes and chart for the NMOCD. 		
7. NU C-prox injection tree & flowline.		
8. RDPU & RU.		FEB 1 5 2008
RUPU 01/10/2008		
RDPU 01/16/2008		HOBBS OCD
I hereby certify that the information above is to ify that any pit or below-grade tank has been/y	true and complete to the best of my knowledge and belief. I further cert will be constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved		
Manda Dohan Liplan		
SIGNATURE	TITLE Administrativ	re Associate DATE 02/14/2008
	hnson	m TELEPHONE NO 806-592-6280
For State Use Only OC DETECT SUPERVISOR/GENERAL MANAGEP		
	Selliania OC DISTRICT SUPERVISORIES	DATE MAR 0 6 2008
CONDITIONS OF APPROVAL IF ANY		



Mark County Sound Doctor Co. of Market Sound Doc

and the probability of the control o