Form 3160-5 (Apri]2004) =


UNITEDSTATES DEPARTMENT OF THE INTERIOR OCD-HOBBS BUREAU OF LAND MANAGEMENT

FORMAPPROVED

OM B No 1004-0137 - Expires March 31, 200)7
5. Lease Serial No	

SUNDRY NOTICES AND REPORTS ON WELLS		NMNM-89874
Do not use this form for proposals to drill or to re-enter an		6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160)-3 (APD) for such proposals	
CURNIT IN TRIBUTATE Office		7. If Unit or CA/Agreement, Name and/or No.
SUBMIT IN TRIPLICATE - Other	instructions on reverse side.	_
1. Type of Well	MAR 0 6 2008	8 Weil Name and No.
	P 8 60 50 50	H W Andrews No 1
2 Nameof Operator Apache Corporation	- HORRS OCT	19 API Well No
3a Address	3b. PhoneNo. (include area code)	30-025-04227
6120 S Yale Ave, Suite 1500 Tulsa OK 741	136-4224 (918)491-4864	10 Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M, or Survey Description)		Eumont; Yates-7 Rvrs-Queen (Gas)
660' FNL & 660' FWL, UL D, S 12, T 20S, I	R 36E	11 County or Parish, State Lea County, NM
12. CHECK APPROPRIATE BOX(E	ES)TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPEOF SUBMISSION	TYPE OF ACTION	
Acidize	Deepen Production (Sta	urt/Resume) Water Shut-Off
Notice of Intent Alter Casing	FractureTreat Reclamation	Well Integrity
Subsequent Report Casing Repair	New Construction Recomplete	Other
Change Plans	Plugand Abandon X Temporarily Ab	andon
Final Abandonment Notice Convert to Inject	tion Plug Back Water Disposal	
following completion of the involved operations. If the optiesting has been completed. Final Abandonment Notices determined that the site is ready for final inspection.) Apache requests to continue TA status on Casing pressure tested 02/19/2008 by Lot	shall be filed only after all requirements, including reclar this well.	nation, have been completed, and the operator has
Copy of MIT chart attached. Original sent to Hobbs Office 02/25/2008.		ACCEPTED FOR RECOF
After $\frac{5-29-08}{}$ the well must or plans to P & A must be subn	nitted.	FEB 2 9 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
1 AST Occol 12/04 2-M	CF	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
Sophie Mackay	Title Engineering Tea	ch
Signature Lophie Markay	Date 02/25/2008	
	FOR FEDERAL OR STATE OFFICE	USE
	c DISTRICT SUPERVIS OFFICE CENERAL MA	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





United States Department of the Interior BUREAU OF LAND MANAGEMENT Carlsbad Field Office



Carisbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220 Tel. (505) 234-597 Fax (505) 234-5927

February 29, 2008

Gentlemen:

Our records indicate that you have a well which is Shut-in (SI) or Temporarily Abandoned (TA). The Bureau of Land Management (BLM) and Minerals Management Service (MMS) definition of a shut-in well is a completion that is physically and mechanically capable of production in paying quantities or capable of service use. The definition of a temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have value as a service completion. According to our records the well referenced above has been shut-in for 6 months or longer. 43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned and requires approval for any well temporarily abandoned for more than 30 days.

Therefore your Sundry Notices are being accepted for record purposes and will not be approved. You need to submit a plan for this well within in 90 days and do one of the following.

- 1. Return the well to production or beneficial use.
- 2. Submit notice of intent to plug and abandon.

Corrective Action to be Completed as follows:

If you decide to **plug and abandon** the well, submit a Sundry Notice (form 3160-5, original and 5 copies) describe the proposed plugging program.

If you decide to return the well to production, submit a Sundry Notice (form 3160-5, original and 5 copies) of intent. Include the date you anticipated the well being placed back in service. 43 CFR 3162.4-1(c) also requires you to notify the Authorized officer, not later than the fifth business day after production is resumed for any well which has been off production for more than 90 days, the date on which such production was resumed. Notification may be by letter or Sundry Notice, or orally followed by letter or Sundry Notice.

If the well is to be used for **beneficial purposes**, submit a Sundry Notice (Form 3160-5, original and 5 copies) include information concerning future use. A brief description of your proposed plans and economic feasibility and an anticipated date for placing the well in beneficial use will suffice. Beneficial use includes, but is not limited to, recompilation to other horizons, conversion to injection for secondary or enhanced recovery, and saltwater disposal or injection.