



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

13-Mar-08

ASHER ENTERPRISES LTD. CO.

12808 LORIEN WAY

OKLAHOMA CITY OK 73170

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

STATE 1 No.001				E-2-24S-34E	30-025-24319-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/12/2008	Routine/Periodic	Buddy Hill	Yes	No	6/15/2008	iLWH0807248900
Violations						
Absent Well Identification Signs (Rule 103)						
Surface Damage/Restoration						
Comments on Inspection: WELL SIGN HAS"NE/SW" NEEDS CHANGED TO "SW/NW",, ALL LEGALS ON WELL SIGN AND @ BATTERY ARE WRONG..NEW SIGN MUST ALSO HAVE API#..ALSO, OILLY SOIL ON EAST SIDE OF IDLE HEATER TREATER AND UN-USED TANKS SHOULD BE REMOVED,,FIRST NOTICE						

STATE 2 No.002				K-2-24S-34E	30-025-24414-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/12/2008	Routine/Periodic	Buddy Hill	Yes	No	6/15/2008	iLWH0807248605
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: WELL SIGN HAS WRONG 1/4-1/4..HAS"SW/NW", NEEDS CHANGED TO "NE/ SW",,ALSO BATTERY SIGN IS ALL WRONG,,FIRST NOTICE						

Oil Conservation Division * 1625 N. French Drive * Hobbs, New Mexico 88240

Phone: 505-393-6161 * Fax: 505-393-0720 * <http://www.emnrd.state.nm.us>

STATE 35 No.001

K-35-23S-34E

30-025-24517-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/12/2008	Routine/Periodic	Buddy Hill	Yes	No	6/15/2008	iLWH0807249468

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: WELL SIGN NEEDS CORRECT "R-34-E" NOT "33"..FIRST NOTICE

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



ASHER ENTERPRISES LTD. CO.
12808 LORIEN WAY
OKLAHOMA CITY OK 73170