



432-586-2453

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

FAX COVER SHEET

NMOCD

Fax 505-393-0720 Office 505-393-6161

TO: Mayo Marrs Attn: Jeri

FROM: Chris Williams

DATE: 3/17/2008

SUBJECT: PA procedure J.F. Black #3

COMMENTS:

Number of Pages + Cover Sheet
2

P#A Procedure.

J. F. Black #3 30-025-11178 G-21-24-37

1980N - 1980E

13" 40# LW 176' - 50SX5

8⁵/₈ 32# LW 1298' - 50SX5

7" 24" 3365 - 125SX5

Top Perf 3365 - Open hole - Shot w/ NITRO

BOS 2550' TOS 1075'

- 1) Set CIBP @ 3300. Dump bail 35' cement ON TOP.
- 2) Perf & squeeze cement @ 2600'. 50' INSIDE & 50' OUTSIDE. TAG
- 3) Perf & Squeeze @ 1298'. 50' inside & 50' OUTSIDE-TAG
- 4) Perf & Squeeze @ 1075'. 50 INSIDE & 50' OUTSIDE-TAG
- 5) Perf & Squeeze @ 176' circulate to surface. 50' inside.
- 6) 10SX5 OR 60' plug @ SURFACE