Submit 3 copies to Appropriate District Office	En	ergy, Minerals and Nati					Form C-103 Revised 1-1-8	
DISTRICT I P.O. Box 1980, Hobbs, NM DISTRICT II	88240 OII	L CONSERVA P.O Box		ON DIVISION	WELL API NO	30-025-06791		
P O Box Drawer DD, Artesia	•	Santa Fe, New M	lexico	87504-2088	5 Indicate Type 6 State Oil / Ga	STATE	FEE 🗸	
1000 Rio Brazos Rd., Aztec,								
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.					7 Lease Name or Unit Agreement Name S.J. SARKEYS '26'			
1 Type of Well OIL WELL	GAS WELL	OTHER DHC #33	26					
2 Name of Operator	CHEVRON USA IN	с /			8 Well No	1 /		
3 Address of Operator 15 SMITH RD, MIDLAND, TX 79705						9 Pool Name or Wildcat PENROSE SKELLY GRAYBURG/TUBB		
4 Well Location							/	
Unit Letter	E : 1980	Feet From The	NORT	TH Line and 660	Feet From Th	ne <u>WEST</u> L	ine /	
Section 26	Tow	nship 21S	R	tange 37E NM	1PM	LEA CO	UNTY	
	10 [Elevation (Show whether DF	, RKB,	RT,GR, etc.) 3389' GL				
11	Check Approp	riate Box to Indicate	e Nat	ure of Notice, Report,	or Other Da			
NOTICE OF I	NTENTION TO					 NT REPORT O	ıF·	
PERFORM REMEDIAL WORK		AND ABANDON		REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF								
PULL OR ALTER CASING CASING TEST AND CEMENT JOB								
OTHER				OTHER	FISH, ACIDIZE,	SCALE SQUEEZE		
Describe Proposed or Coproposed work) SEE RU		s (Clearly state all perti	nent de	etails, and give pertinent d	ates, including (estimated date of st	arting any	
12-03-07. MIRU. CHANGE FROM ROD TO TBG TOOLS. 12-04-07. TIH W/FREE POINT STUCK @ 5942 CUT TBG @ 5825 TIH W/FREE POINT & SET DN @ 5909 TBG FREE @ 5625.								
12-05-07 [.] CUT TBG @ 5634. 12-06-07 [.] TIH TO 3930. TAG UP. WRK DN TO 3962 PU BIT & TAG @ 3962 TURN DN TO 4227. FELL OUT TIH TO 4443. SET DN								
12-07-07: TIH W/TBG TO 4443. TIH W/TBG TO TOF@ 5634 12-10-07: TAG FISH @ 5634. LATCH ON. JAR ON FISH @ 5589 12-11-07. TOF @ 5917. TIH W/30 STANDS TBG								
12-12-07 TIH W/TBG. TAG @ 5840 WORK THRU. TAG @ 5857. TURN TBG. WORK DN TO 5872. EOT @ 5825. C/O FR 5840-5879, HARD FR 5879-5891 C/O TO TOF @ 5922. 12-13-07 [.] TAG FISH @ 5922 12-17-07. TAG TOF @ 5962 C/O @ 6050.								
12-18-07. TAG FISH @ 5976. TURN W/TONG DN TO 5980. PULL TO 80 PTS. PULL FREE. 12-19-07 TIH& TAG @ 5934. TIH W/BIT & TAG @ 6030. 12-20-07. TAG @ 6040 12-21-07. CIRC W/FOAM AIR C/O TO TD @ 6278 12-26-07: TIH W/PKR & SET @ 5828. PUMP 3000 GALS 15% HCL ACR PERFS 5926-6246. 12-27-07. SWABBING								
01-02-08: BLED GAS ON TBG & CSG DN.PMP 40 BBLS 10# DN TBG & REL RBP 01-03-08. TIH W/RBP & PKR. SET RBP @ 3980 01-04-08: ACIDIZE PERFS 3693-3922 W/4000 GALS 15% HCL REL PKR TIH TO BTM PERF. PUH. SET PKR @ 3660								
01-07-08: PUMP 3 DRUMS 01-10-08 TIH W/RODS PI	S RE-4777 SCALE I	NHIB. 01-08-08. REL I	RBP V	WELL ON VAC. 01-09-08	SET TAC IN 1	10 PTS TENSION	RT	
RECEIVED								
					JAN 15	2008		

HOBBS OCD

I hereby certify that the information above is true	e and complete to the best of my knowledge and bel	ef		
SIGNATURE SUNSE) Junkerton T	ITLE Regulatory Specialist	DATE	1/14/2008
TYPE OR PRINT NAME	Denise Pinkerton		Telephone No	432-687-7375

.MAR. 1. 1. 8. 2008