Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DI	ST	RI	CT	1

P O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O Box Drawer DD, Artesia, NM 88210

D

1(

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

30-025-31204 Indicate Type of Lease

WELL API NO

	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
ISTRICT III	6 State Oil / Gas Lease No
000 Rio Brazos Rd , Aztec, NM 87410	NM-878
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.	7 Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT
Type of Well OIL GAS WELL OTHER CO2 & WTR INJECTION	
Name of Operator CHEVRON USA INC	8 Well No 345 /
Address of Operator 15 SMITH RD, MIDLAND, TX 79705	9 Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES
Well Location Unit Letter N 1310 Feet From The SOUTH Line and 1850	Feet From The WEST Line
Section 31 Township 17S Range 35E N	MPM LEA COUNTY

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

10 Elevation (Show whether DF, RKB, RT,GR, etc.)

NOTICE OF IN	TENTIC	ON TO:	SUBS	EQUE	INT REPORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	✓	ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING OPERAT	ION 🗌	PLUG AND ABANDONMENT	
PULL OR ALTER CASING			CASING TEST AND CEMENT JO	в 🗌		
OTHER			OTHER REL	PKR, TC	OH W/TBG (CHART)	_

3986' GR

RECEIVED

FEB 13 2008

HOBBS OCD

I hereby certify that the information above is	s true and complete to the best of my knowledge and	l belief			
SIGNATURE	se succet ton	TITLE	Regulatory Specialist	DATE	2/12/2008
TYPE OR PRINT NAME	Denise Pinkerton		,	Telephone No	432-687-7375

APPROVED

MIS WILLIAM OC DISTRICT SUPERVISOR/GENERAL MARVAGER
DA DATE

MAR 18 2008

¹² Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103


^{01-10-08:} MIRU. PMP 10# BRINE DN TBG.

^{01-11-08:} WORK PKR - WOULD NOT TURN LOOSE WORK TBG UP & DOWN W/TORQUE. MOVE PKR UP HOLE 6'.

^{01-12-08. 0} PSI ON TBG

^{01-14-08°} FND PKR @ 3792. SHOT 4 HOLES IN TBG @ 3785. CSG FLOWING. PMP 110 BBLS 16# MUD DN CG & 20 BBLS 16# MUD DN TBG. LAID DN 135 JTS 2 7/8" TBG. PU NEW 7" PKR W/ON/OFF TOOL & PUMP OUT PLUG PU 135 JTS TO SET PKR @ 4220.

^{01-15-08.} PRE TEST CSG TO 520# LOST 10# IN 15 MINS CIRC 155 BBLS BW PKR FLUID. LATCH ONTO PKR CHART TEST CSG TO 530# FOR 35 MINS. GAIN 25# TO 555#. SHEAR PUMP OUT PLUG @ 1400#. TEST TREE TO 3000#. NO LOSS. RIG DOWN. (ORIGINAL CHART & COPY OF CHART ATTACHED).



HIGHO DEPTH HIGH SHOULD FROM SHOULD S

DATE VIS/08

WELL NAME CVV #345

SUPERVISOR GALL ISM

PACKER TYPE ARROW Set IX 7"x2 %"

PACKER SETTING DEPTH 4218"

PERFORATIONS 4309'- 4590'