Form 3160-5 (April 2004)

## OCD-HORRS **UNITED STATES** DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

OM B No 1004-0137 Expires. March 31, 2007

5 Lease Serial No NMNM030941 27573

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED

1 Type of Well Gas Well Oll Well Gas We	8. Well Name and No. Bate Federal #3  9. API Well No. 30-025-22597  10. Field and Pool, or Exploratory Area		
3a Address 3b. Phone No. (include area code)	9. API Well No. 30-025-22597		
50. I none inc. (menue area code)			
550 W. Texas Ave., Suite 1300 Midland, TX 79701 432-685-4395			
4 Location of Well (Footage, Sec., T, R, M, or Survey Description) 330' FNL & 1980' FWL Sec.35, T19S, R33E, Unit C	SWD; Yates  11. County or Parish, State  Lea, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION	TYPE OF ACTION		
□ Notice of Intent       □ Acidize       □ Deepen       □ Production         □ Alter Casing       □ Fracture Treat       □ Reclamation         □ Casing Repair       □ New Construction       □ Recomplete         □ Change Plans       □ Plug and Abandon       □ Temporanly         □ Convert to Injection       □ Plug Back       □ Water Dispose	Other Cement Squeeze Csg y Abandon Leak		

all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection )

See Attached

RECEIVED

MAR 1 0 2008

HOBBS OCD

ACCEPTED FOR RECORD

7 2008

BUREAU OF LAND MANAGEMENT CADLODAD EIELD OFFICE

		CAKESDAD FIELD OFFICE
14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)	]	
Carol Ann Lance	Title	Regulatory Analyst
Signature Carol On Lance	Date	01/30/2008
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		
The state of the s		PERVISOR/GENERAL MANAGEP MAR 2 6 2008
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject leg which would entitle the applicant to conduct operations thereon	nt or	Office
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		

## COG Operating LLC - Bate Federal #3- API # 30-025-22597- Cement Squeeze Casing Leak

- 12-17-07 MIRU. Release Pkr & POOH.
- 12-20-07 Perf 4 shots @ 395'. RIH w/RBP set @ 2,800'.
- 12-21-07 Pump 100 sxs Class C cement. Drop rubber plug, pump down to 350'.
- 12-26-07 Drill plug & cement from 250'-420'.
- 12-27-07 Release RBP & POOH.
- 01-05-08 Drill Cement & junk from 3181'-3366'.
- 01-09-08 Drill Cement & junk to 3494'. POOH w/bit. RIH w/6 1/4" window mill . Mill to 3500'.
- 01-10-08 Mill to 3514' TD. Dump 1000# oyster shells down csg w/water.
- 01-14-08 Notified OCD & BLM. Pat McKelvey w/Hobbs BLM witnessed. Tag Oyster shell plug @ 3485'.

  Cement w/350 sxs Super C cmt & 75 sxs Class C neat cmt.
- 01-15-08 Cement top @ 2900' Perf 4 shots @ 2875'.
- 01-16-08 Pump 820 sxs Class C cement.
- 01-17-08 Cement top @ 630'. Drill out to 2834'. Pat McKelvey w/Hobbs BLM witnessed job.
- 01-18-08 RIH w/ Cement Retainer & set @ 2861'.
- 01-19-08 Pump 200 sxs Class C cement.
- 01-20-08 Pump 200 sxs Class C & 75 sxs Class C neat cmt. Cemented bottom 21 jts of tbg.
- 01-21-08 Drill out cement retainer.
- 01-22-08 RIH w/12# Class C cmt plug & set @ 2922, pull up to 2544'.
- 01-23-08 Drill cement from 2554' to 2858'.
- O1-24-08 Drill Cement from 2858' to 2930'. Drill out float collar, guide shoe & oyster shells to 3515'.

  RIH w/Pkr & set @ 3248'.
- O1-25-08 Acidize w/3000 gals. Iron control 15%. Release Pkr & POOH. RIH w/PC AD-1 5" pkr, 2 3/8" XO, 111 jts 2 7/8" PC J-55 6.5# EUE tbg. Set Pkr @ 3440'. Pressure to 500 psi for 30 min. record on Chart. RDMO.