Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 Revised March 25, 1999
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II	OIL CONCEDIATION DIVICION		30-025-30977
1301 W. Grand Ave., Artesia, NM 88210 District III	Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410			STATE STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr., Santa Fe, NM	Danta 1 C,	INIVI 6/303	V-2199
87505			
SUNDRY NOTIO	CES AND REPORTS ON '		7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICA			
PROPOSALS.) 1. Type of Well:	•		
Oil Well Gas Well	Other Disposal	JAN 3 1 2008	Gem, 8705 JV-P
2. Name of Operator			8. Well No.
BTA Oil Producers	003002	<u>OCD-ARTESIA</u>	3 /
3. Address of Operator	701		9. Pool name or Wildcat SWD, Delaware
104 S. Pecos, Midland, TX 797 4. Well Location	/01		SWD, Delaware
4. Well Location			
Unit Letter O :	660 feet from the	south line and	1980 feet from the east line
		.a. ba.F.)
Section 2		OS Range 33E ether DR, RKB, RT, GR, etc	NMPM Lea County
	3579' GR	einer DK, KKB, K1, GK, ei	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON	☐ REMEDIAL WOR	
TEMPORARILY ABANDON TO TEMPORARILY ABANDON TEM	CHANGE PLANS		ILLING OPNS.
TEMPORARIET ABANDON	CHANGE FEARS		ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB	ND
OTHER: Pull and repair		☐ OTHER:	· · · -
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
starting any proposed work). SEI recompilation.	E RULE 1103. For Multip	le Completions: Attach w	ellbore diagram of proposed completion or
BTA Oil Producers proposes the following:			
Well has possible hole in tubing or a packer leak. Will pull to determine problem and repair.			
•			CONTROL OF THE REAL ASSESS PRODUCTION
			RECEIVED
•			
			FEB - 5 2008
			HOBBS OCD
			HUDDS UUD
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE PM (M)	1000/	ΓLE <u>Regulatory Admi</u>	DATE 01/20/09
SIGNATURE TUNN	11	TLE <u>Regulatory Admi</u>	nistrator DATE 01/29/08
Type or print name Pam Inskeep	pinskee	p@btaoil.com	Telephone No. (432) 682-3753
(This space for State use)	_	^	
APPPROVED BY	TIT	rle <u>Geologist</u>	DATEMAR 2 8 2009
Conditions of approval, if any:		0 00,000	