Do not	BUREA	UNITED STATES TMENT OF THE INTERIOR U OF LAND MANAGEMENT FICES AND REPORTS ON W m for proposals to drill or to re the Horm 3160-3 (APD) for suc			FORM APROVED OMB NO 1004-0135 EXPIRES. NOVEMBER 30, 2000 5. Lease Serial No <u>NMNM89891</u> 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE MAR 2.5 2008					7 Unit or CA Agreement Name and No		
1a Type of Well 🖸 Oil Well 🗍 Gas Well 🗋 Other					8 Well Name and No.		
2. Name of Operator					Cockburn Federal 2		
DEVON ENERGY PRODUCTION COMPANY, LP 7					30-025-36282		
20 North Broadway, Oklahoma City, OK 73102 405-552-8198					10 Field and Pool, or Exploratory		
 Location of Well (Report location clearly and in accordance with Federal requirements)* 					Mescalero Escarpe-Bone Spring		
660 FSL & 660 FWL UNIT M					12. County or Parish 13. State		
SEC 10 T18S R		(LEA	<u>NM</u>	
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OS SUBMISS	SION				on (Start/Resume)	Water Shut-Off	
Notice of Intent		Acidize	Deepen 🗌 Fracture Treat	Reclamat	•	Well Integrity	
Subsequent Report		Casing Repair	New Construction	New Construction		✓ Other Add Bone	
Final Abandonment Notice		Change Plans	Plug and Abandon Plug Back	U Tempora	arily Abandon Spring		/
determined that the site is ready for final inspection) 1/04/08 - 2/05/08 MIRU. PU and unseat pump. POOH with pump, rods, and tubing. RIH with bit and scraper. RIH with perforating gun and perforate 2 spf from 8671-9129'. POOH and RD. RIH with RBP and packer. Set RBP at 9289'. Tested RBP to 3000 psi - held good. Set packer at 8589'. Loaded casing and pressured to 1000 #. RU and acidize well with 3500 gallons 15% HCI. RD. Flow well back. Released packer and POOH with tubing and packer. ND BOP and NU frac valve. MIRU casing saver. Frac well with 102,000 gallons 10 # Brine with 2500 # 100 Mesh White sand, 2500 # 20/40 White sand, 11,000 # 14/30 Liteprop C and 9000# 16/30 Siberprop and flushed with 8400 gallons 10 # Brine. RD Took off frac valve and NU BOP. Washed sand and circulate clean. Released RBP and pulled out of hole with RBP and tubing. MIRU. Perforate upper Bone Springs at 8527-8261'; 8266- 8275'; 8292-8296'; 8300-8307'; and 8342-8352'. 1 spf. RD. RIH with RBP and packer on tubing. Set RBP at 8524' and pulled packer up and set. Tested RBP to 3000 psi - held good. Pulled packer up to 8196' and set. Tested casing to 1000 psi - held good. RU and acidize with 4,000 gallons 15% NeFe. RD. Flow well back. RU and swab. Release packer and POOH with tubing and packer. ND BOP and NU Frac valve. MIRU. Frac with 58,000 gallons Spectra Star 2600 and 79,500 # 16/30 White sand and 20,000 # 16/30 Siberprop sand. RD. RIH with tubing, pump, and rods. Hang well on production RDMO							
14 Hereby certify that the foregoing is true and correct							
Signed	X	Na	me Norvella Ada le Sr. Staff Engineering		ACCFPTE) F_{4}	ORD
(This space for Federal or State Office use)							
Approved by Conditions of approval, if a	<u>, 1/11</u> ny.	leane OC DISTRIC	E SUPERVISOR/GENER/		MAF		
its jurisdiction	sita crime ior a	hy person knowingly and williaky to ma	ke any department of agency of the Onit	eu states any fai		presentations to	
		*	See Instruction on Reverse S	Side	BUREAU OF	LAND MANAGEIN	EINT

າມາ