UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-I	HOBBS
-------	-------

FORM APPROVED OMB NO 1004-0137

SUNDRY NOTICES AND REPORTS ON WELLS

Expires March 31, 2007

5 Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		NMLC031740B 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side		7. If Unit or CA/Agreement, Name and/or No NM - 70948A 8. Well Name and No EUNICE MONUMENT SOUTH UNIT #238				
1 Type of Well X Oil Well Gas Well Other 2 Name of Operator XTO Energy Inc.						
3a Address 200 N. Loraine, Ste. 800 Midland.	TX 79701	3b Phone No. (<i>include a</i> 432,620,6709	•	9 API Well N 30-025-04	466	
UNIT LTR: I 2200 feet from the South line & 440 feet from the East line. Section: 4 Township: 21S Range: 36E			10. Field and Pool, or Exploratory Area 23000 / 11 County or Parish, State 1EA / nm			
12. CHECK APPROPRIATE	BOX(ES) TO IND	DICATE NATURE OF	NOTICE, REPO	ORT, OR OT	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production Reclamatio Recomplete Temporarily	;	Water Shut-Off Well Integrity X Other Acid stimulate: Possible	
13. Describe Proposed or Completed Operation (clearly	Convert to Injection		Water Disp		chem squeeze	
Describe Proposed or Completed Operation (clearly state all pertment details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones following completion of the involved operations. If the operation results in a multiple completion or necompletion in a new interval, a Form 316-04 shall be filled within 30 days testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has determined that the final sits is ready for final inspection.) The purpose of this intent request is to clean out, acid stimulate & possible chemical squeeze the subject well. I. MIRUPU. RIH & tag for fill. Pu & RIH w/ Sonic Hammer on 2-7/8 J-55 tbg. RU acidizing equipment. OH fr 3,748' to 3,855'w/185 bbls of 9# brine. Circ Hole Clean. Acidize OH w/3,500 gals of 20% 90/10 HCL (approx 32 bbls per stand). Flush acid w/ 25 BS. Drop ball to shift sleeve in tool. RU swab. Determine flow rate. If pump, rods &/or tbg show signs of scale buildup, a chem squeeze procedure will be designed. RWTP RWTP FEB - 6 2008						
FEB 1 1 2008 LES BABYAK PETROLEUM ENGINEER						
14. I hereby certify that the foregoing is true and correct		BBS OC			about the con-	
Name (Printed/Typed) Sherry Pack		Regulat	tory Analyst	70		
_ Surry tack		Date 1/15/2008				
	SPACE FOR FEDE	RAL OR STATE OFF	ICE USE			
Conditions of approval, if any, are attached Approval of t certify that the applicant holds legal or equitable title to the which would entitle the applicant to conduct operations there	his notice does not war lose rights in the subjection.	t lease	· · · · · · · · · · · · · · · · · · ·	<u>_</u>	RPR 0 2 2008	
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section States any false, fictitious or fraudulent statements or repres	1212, makes it a crime fentations as to any matter	or any person knowingly ar er within its jurisdiction	nd willfully to make	to any departn	nent or agency of the United	