Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-	103
District I	Energy, Minerals and Natural Reso	urces May 27, 2	2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II 1301 W. Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISI	ION 30-025-21163	
<u>District III</u>	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease	
1220 S St Francis Dr., Santa Fe, NM	,	58102	
87505	ICES AND REPORTS ON WELLS	7 1 N Ti-i4 A AN	
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK T CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Nam Flying M San Andres Unit	ne
PROPOSALS.) 1 Type of Well: Oil Well	Gas Well ☐ Other ⊠ P&A'd wellbore	8. Well Number 13-4 134 -	-
2. Name of Operator	Gas went Grand Tank a wendore	9. OGRID Number	
SOUTHWEST ROYALTIES, INC	UTHWEST ROYALTIES, INC.		
3. Address of Operator		10. Pool name or Wildcat	
6 DESTA DRIVE, STE 2100, MII	DLAND, TEXAS 79705	Flying M San Andres	
4. Well Location			
i e	660_feet from theN line and		
Section 20	Township 9S Range 33F		
The Control of the Co	4372' GR	F, GR, etc.)	
Pit or Below-grade Tank Application 🗌			
Pit typeDepth to Groundw	aterDistance from nearest fresh water well	Distance from nearest surface water	ľ
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material	
12. Check A	Appropriate Box to Indicate Nature of	Notice, Report or Other Data	
NOTICE OF IN	ITENTION TO		
PERFORM REMEDIAL WORK	ITENTION TO: PLUG AND ABANDON □ REMED	SUBSEQUENT REPORT OF:	J1
TEMPORARILY ABANDON		DIAL WORK ALTERING CASING ENCE DRILLING OPNS. P AND A	Ш
PULL OR ALTER CASING		G/CEMENT JOB	
_			
OTHER:	OTHER		
13. Describe proposed or comp	pleted operations. (Clearly state all pertinent of	details, and give pertinent dates, including estimated	l date
or recompletion.	ork). SEE RULE 1103. For Multiple Comple	etions: Attach wellbore diagram of proposed comple	etion
or recompletion.			
REQUEST FOR FINAL INSPECTI	ON.		
I hamber contify that the information	-1	1	
rate tank has been/will be constructed or	closed according to NMOCD guidelines . a genera	knowledge and belief. I further certify that any pit or be I permit or an (attached) alternative OCD-approved plan	elow-
\sim		, 10	⊔.
SIGNATURE Lewin	TITLE OPERAT	TIONS ASSTDATE_2/08	
Type or print name DAWN M. H	OWARD F-mail address: dhoward@clay	rtonwilliams.com Telephone No. 432/688-3267	
For State Use Only		1 1 clephone 140. 432/086-3207	
····	YVI aloud Ma	OUTA / SILL of	_
APPROVED BY:	THIE A	DATE 3/4/200	8
Conditions of Approval (if any):	J	•	
	COMPLIANCE OF	FICER	
		<u> Derenen</u>	
	•	HEVEIAER	

Insp. 3/4/2008

MAR 0 4 2008

HOBBS OCD



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

14-Aug-2007

SOUTHWEST ROYALTIES INC
6 DESTA DRIVE
SUITE 2100
MIDLAND,TX 79705-

Property: FLYING M SA UNIT

B-20-9S-33E 30-025-21163-00-00

134

Form C-103, Report of Plugging has been approved as to plugging of the Well Bore. Liability under bond is retained until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been remediated, filled and leveled.
2. Rat hole and cellar have been filled and leveled.
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been remediated, leveled and cleared of all junk & equipment.
7. All environmental concerns have been addressed as per OCD guidelines.
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected.
When all of the work outlined above has been done, please notify this office by completing, signing and

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

returning this letter to us so that our representative will not have to make more than one trip to the location.

Name Jum novoce

Title 9 08 429/08