

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33540 ✓
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator PIERCE PRODUCTION COMPANY, L.L.C. ✓		6. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 2079 Midland, Texas 79702-2079		7. Lease Name or Unit Agreement Name Vinson ✓
4. Well Location Unit Letter N : 330 feet from the South line and 2310 feet from the West line Section 4 Township 20S Range 38E NMPM County Lea		8. Well Number 001 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3574' GR		9. OGRID Number 017733 ✓
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Preparing for Re-Entry Operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12-17-2007: Arrive location, wait on welder, Cut additional section of surface casing off, chip out additional cement and expose additional 8 5/8" intermediate casing. Make installation cut on 8 5/8" intermediate casing and install 8 5/8" slip-on collar. Shut down due to darkness.

12-18-2007: Arrive location, remove new collar, take measurement for 8 5/8" extension joint, weld plate and eclose 8 5/8" x 13 3/8" annulus. Install 1" collar in same; shut down due to darkness.

12-19-2007: Arrive location, remove new collar, install 8 5/8" extension joint, weld same into 8 5/8" slip-on collar. Install 11", 3000# WP x 8 5/8" slip-on "A" section wellhead. Weld on head, set cellar back in.

RECEIVED

MAR 27 2008

HOBBS OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Bill Pierce TITLE Vice President DATE 12/21/2007

Type or print name Bill Pierce
For State Use Only

E-mail address: bill@pierceproduction.net Telephone No. (432)570-6009

APPROVED BY: [Signature] TITLE Geologist DATE APR 11 2008

Conditions of Approval (if any):