

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

March 4, 2004

WELL API NO.

30-025-05562

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

JO

8. Well Number

2

9. OGRID Number

13046

10. Pool name or Wildcat

EUMONT QUEEN Yates, 7 RURS

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐

Gas Well ☒

Other ☐

2. Name of Operator

LANEXCO, INC.

3. Address of Operator

1105 WEST KANSAS, JAL, NM 88252

4. Well Location

Unit Letter M : 990 feet from the SOUTH line and 990 feet from the WEST line

Section 6

Township 19S Range 37E

NMPM

County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well

Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;

 feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well was TA'D 12-18-06.

We propose to permanently abandon this well as soon as Mayo Marrs Casing Pullers can schedule.

* Plugging procedure attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles L. Mann TITLE Production Supt. DATE 4-21-08

Type or print name CHARLES MANN

E-mail address:

Telephone No 505-395-3056

(This space for State use)

OCD DISTRICT SUPERVISOR/GENERAL MANAGER

APPROVED BY Chris Williams TITLE DATE APR 24 2008

Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS


Lanexco, Inc.
1105 West Kansas
Jal, New Mexico 88252
505/395-3056
Fax 505/395-3205

LANEXCO, INC.

PLUGGING PROCEDURE
JO NO. 2
30-025-05562
LEA COUNTY, NM

1. Move in rig up plugging equipment.
2. Tag plug at 3515 with tubing. Pull out of hole with production tubing.
3. Load hole with salt gel.
4. Set 100' plug at salt base 2620-2520. WOC and tag.
5. ~~Perf and squeeze 50' out and in F/1450-1550 (Top of salt). WOC and tag.~~
1479'
6. Perf at 1379' and circulate to surface.
7. Cut off well head. Set marker.

JO No. 2
Plug & Abandon



← 8⁵/₈" 28# @ 1429' cmt'd w/ 650 SXS

← TOL @ 3515'

← 5¹/₂" CIRP @ 3550'

} Csg Perfs: 3600-3625, 3636-3645, 3672-3688, 3700-3770,
3782-3824, 3832-3862.

← 5¹/₂" 14# @ 3884' cmt'd w/ 1260 SXS, Top @ 1630'