

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103

March 4, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-025-28086

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

ONEY

8. Well Number

1

9. OGRID Number

13046

10. Pool name or Wildcat  
EUMONT GAS

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐

Gas Well ☒

Other

2. Name of Operator

LANEXCO, INC.,

3. Address of Operator

1105 WEST KANSAS, JAL, NM 88252

4. Well Location

Unit Letter D : 660 feet from the NORTH line and 660 feet from the WEST line

Section 9

Township 19S Range 37E

NMPM

County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3693.3 GL

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL      Sect      Twp      Rng      Pit type      Depth to Groundwater      Distance from nearest fresh water well     

Distance from nearest surface water      Below-grade Tank Location UL      Sect      Twp      Rng      ;

     feet from the      line and      feet from the      line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well is to be plugged as soon as Smith and Marrs Casing Pullers can get it on their schedule.

\* Plugging procedure attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles L. Mann TITLE Production Supt. DATE     

Type or print name CHARLES MANN

E-mail address:     

Telephone No. 505-395-3056

(This space for State use)

APPROVED BY Chris Williams TITLE OCD DISTRICT SUPERVISOR/GENERAL MANAGER DATE APR 24 2008

Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS

Lanexco, Inc.  
1105 West Kansas  
Jal, New Mexico 88252  
505/395-3056  
Fax 505/395-3205

# LANEXCO, INC.

## Plugging Procedure

ONEY NO. 1  
30-025-28086  
Eumont Pool  
Lea County, NM

1. Move in and rig up plugging unit and equipment.
2. Run in hole with work string and tag existing plug at 2700' / CAP w / 25 sx cmt
3. Load hole with salt gel.  
SET 100' plug or 25sx 2650-2550' (BASE of Salt)
4. Set 100' plug or 25 sx, which ever is greater 1250'-1150'. WOC and tag.  
1550'-1450'
5. Set 100' plug or 25 sx, which ever is greater 360'-260'. WOC and tag.  
450'-350'
6. Set 30' surface plug. Cut off head and set hole marker. Cut off anchors.  
60'

ONEY No. 1

8/4/06

← 8 5/8" csy set @ 402'

← 10' cmt @ 2700'

← CIBP @ 2710'

← Perf's: 2775' - 3038'

← Perf's: 3392' - 3452'

← Queen Perf's: 3774' - 3834' (14 perf's)

← PBTD @ 3909'

← 5 1/2" csy set @ 3944'