State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERVATION DIVISION	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-07521
DISTRICT II	,	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE FEE X
DISTRICT_III		6. State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICE	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (Form C-101) for such proposals.)	Section 32
1. Type of Well: Oil Well X	Gas Well Other	8. Well No. 231
2. Name of Operator		9. OGRID No. 157984
Occidental Permian Ltd.		10. Pool name or Wildcat Hobbs (G/SA)
3. Address of Operator	22	10. Foot name of Windows (G/S/N)
HCR 1 Box 90 Denver City, TX 793.	23	
	Feet From The South 2310	Feet From The West Line
Section 32	100	8-E NMPM Lea County
	1. Elevation (Show whether DF, RKB, RT GR, etc.) 3632' GL	
Pit or Below-grade Tank Application	or Closure	
	ter Distance from nearest fresh water well	Distance from nearest surface water
l .	low-Grade Tank: Volume bbls; Construction	
Pit Liner Thickness mil Bei	low-Grade Tank: Volume bots, Construction	Wiaterial
	propriate Box to Indicate Nature of Notice, Report, of	or Other Data
NOTICE OF INTENT	FION TO: 50	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK X PL	LUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CH	HANGE PLANS COMMENCE DRILLING	OPNS. PLUG & ABANDONMENT
DULL OR ALTER CASING MI	uttiple Completion CASING TEST AND CEN	MENT JOB
	ultiple Completion CASING TEST AND CEN	MENT JOB
OTHER.	OTHER:	
OTHER. 13 Describe Proposed or Completed Operation		ates, including estimated date of starting any
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For I	OTHER: ons (Clearly state all pertinent details, and give pertinent details)	ates, including estimated date of starting any
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 11. Kill well.	ons (Clearly state all pertinent details, and give pertinent details and give pertinent details and give pertinent details.) Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1 1. Kill well. 2. POOH w/production equipment.	ons (Clearly state all pertinent details, and give pertinent details and give pertinent details and give pertinent details.) Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs.	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs.	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion.
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production.	OTHER: ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propositing.	ates, including estimated date of starting any ed completion or recompletion. APR 1 4 2003 OBBS OCD
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For late 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production.	ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propos	ates, including estimated date of starting any ed completion or recompletion. APR 1 4 2003 OBBS OCD
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production.	OTHER: Ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propositing.	ates, including estimated date of starting any ed completion or recompletion. APR 1 4 2003 OBBS OCC Tufy that any pit or below-grade tank has been/will be
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production.	OTHER: ons (Clearly state all pertinent details, and give pertinent details). Multiple Completions: Attach wellbore diagram of propositing.	ates, including estimated date of starting any ed completion or recompletion. APR 1 4 2003 OBBS OCC Tufy that any pit or below-grade tank has been/will be
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production.	ons (Clearly state all pertinent details, and give pertine	ates, including estimated date of starting any ed completion or recompletion. APR 1 4 2003 OBBS OCC Tufy that any pit or below-grade tank has been/will be
OTHER. 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For 1. 1. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tub. 6. Return well to production. I hereby certify that the information above is true a constructed or closed according to NMOCD guidelines. SIGNATURE	ons (Clearly state all pertinent details, and give pertine	APR 1 4 200°2 Tify that any pit or below-grade tank has been/will be ative OCD-approved DATE 04/10/2008
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For It I. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tube. 6. Return well to production. I hereby certify that the information above is true a constructed or closed according to NMOCD guidelines. SIGNATURE TYPE OR PRINT NAME Mendy A. Johns For State Use Only	ons (Clearly state all pertinent details, and give pertine	APR 1 4 2003 APR 1 4 2003 Tufy that any pit or below-grade tank has been/will be ative OCD-approved Tive Associate DATE 04/10/2008 2006 TELEPHONE NO 806-592-6280
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For It I. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tube. 6. Return well to production. I hereby certify that the information above is true a constructed or closed according to NMOCD guidelines. SIGNATURE TYPE OR PRINT NAME Mendy A. Johns For State Use Only	ons (Clearly state all pertinent details, and give pertine	APR 1 4 200° APR 1 4 200° Tity that any pit or below-grade tank has been/will be ative OCD-approved Tity Associate DATE 04/10/2008 TELEPHONE NO 806-592-6280
13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For It I. Kill well. 2. POOH w/production equipment. 3. Clean out well to PBTD @3952'. 4. Acid stimulate open perfs. 5. Run back in hole w/new packer and tube. 6. Return well to production. I hereby certify that the information above is true a constructed or closed according to NMOCD guidelines. SIGNATURE TYPE OR PRINT NAME Mendy A. Johns For State Use Only	ons (Clearly state all pertinent details, and give pertine	APR 1 4 2003 APR 1 4 2003 Tufy that any pit or below-grade tank has been/will be ative OCD-approved Tive Associate DATE 04/10/2008 TELEPHONE NO 806-592-6280