## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. , NM 87505	WELL API NO. 30-025-28349	
DISTRICT II	Santa I C,	, 14141 67303	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No	TEE A
1000 Rio Brazos Rd, Aztec, NM 87410			o. State Off & Gas Lease No	
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit Agree	ment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 9	
1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned			8. Well No. 146	/
2. Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	H-l-l- (C/CA)
HCR 1 Box 90 Denver City, TX	79323		10. I our name of windcat	Hobbs (G/SA)
4. Well Location				
Unit Letter D : 75	Feet From The North	Fe	et From The West	Line
Section 9	Township 19-S	Range 38-	E NMPM	Lea County
	11. Elevation (Show whether DF, R	KB, RT GR, etc.)		
	3600' GL			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
TH Ellief Thicknesshill	Below-Grade Talik. Volume	bois; Construction Ma	ateriai	
12. Checi	k Appropriate Box to Indicate Na		Other Data SEQUENT REPORT O	E.
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	<del></del>	
			ALTERINO	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP		ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN			NT JOB	
OTHER: Return well to production	X	OTHER:		
<ul><li>13. Describe Proposed or Completed Opproposed work) SEE RULE 1103.</li><li>1. Kill well</li><li>2. Test casing to 1000 PSI.</li></ul>	For Multiple Completions: Attach w	etails, and give pertinent dates ellbore diagram of proposed	s, including estimated date of s completion or recompletion.	starting any
3. Drill out CIBP @4067'. Clean out	well to 4275'.		RECEIVE	
<ul><li>4. Perforate well.</li><li>5. Acid treat all perforations.</li></ul>			HEVERAF	
6. Perform scale squeeze.				
7. RIH w/ESP equipment.			MAR 2 4 2008	
8. Return well to production.			HAN 2 7 2004	
			HOBBS O	CD
I hereby certify that the information above is to constructed or	rue and complete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank h	nas been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	I
SIGNATURE MONDAY TITLE Administration Associate DATE CONTRIBUTION				
TAUDE OF PROPERTY AND	ohnson E-mail address:	TITLE Administrative		
For State Use Only				
	College OCD	TSTEET SUPERVISOR	GENERAL MANAGERA	PR 2 5 2008
APPROVED BY	Villem	TITLE	DAT	F.

CONDITIONS OF APPROVAL IF ANY: