
## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-271	38
<u>DISTRICT II</u>	Santa Fe,	TATAT 0.1202	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6 State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	TIOTO AND DEDORTO ON WE	CT T C	7 Lange Name as that As as	ment Name
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals )			Section 19	
1. Type of Well:			8. Well No. 142 /	
Oil Well Gas Well Other Injector  2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.			/	
3. Address of Operator HCR 1 Box 90 Denver City, TX	X 79323		10. Pool name or Wildcat	Hobbs (G/SA)
4 Well Location			1	
Unit Letter M . 1200	Feet From The South	1300 Fee	et From The West	Line
Section 19	Township 18-S	Range 38-E	E NMPM	Lea County
	11. Elevation (Show whether DF, R. 3659' GL	KB, KI GK, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Chec	k Appropriate Box to Indicate Na	ature of Notice, Report, or C	Other Data	
NOTICE OF INT			SEQUENT REPORT O	F: '
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	G CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP			NS. PLUG & A	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB	
OTHER.		OTHER: HCP		. X
13. Describe Proposed or Completed Op				starting any
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. RUPU & RU. Kill well. NU BOP/ND wellhead.				
2. RU wireline & set blanking plug.				
3. POOH w/tubing & packer.	MEGETVI			
<ol> <li>RIH w/Arrowset 1-X packer on 12</li> <li>ND BOP/NU wellhead.</li> </ol>	4 jts of 2-7/8" tubing. Packer set	@4090°.		
6. Test casing to 550# and chart for the 7. RDPU & RU. Clean location.	ne NMOCD.		MAR 2 4 2009	! }
7. ADFU & KU. Clean location.			IIODOC	700
			HUBB5 (	
I hereby certify that the information above	true and complete to the barrier	ladge and hall C. T.C. d.		
I hereby certify that the information above is constructed or		ieage and beliet. I further certify t	tnat any pit or below-grade tank l	nas been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	
SIGNATURE Mendy Clash TITLE Administrative Associate DATE 03/21/2008				
TYPE OR PRINT NAME Mendy A. Je	/ / / / / / / / / / / / / / / / / / / /	mendy_johnson@oxy_com	TELEPHONE NO.	05,21,2000
For State Use Only				
APPROVED BY Muse	William OCD	HISTRICT SUPERVISOR/G	FENERAL MANAGER	APR 25 200a
APPROVED BY				



0xy NHV # 19-142 2-20-08 2-20-08 611 Humphrey Chart recorder # 12511 125/101744 1-15-08

5.4