rom 3100-3	UNITED STATES PARTMENT OF THE INTERIOR	OCD-HOBBS	FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007
SUNDRY MAR 16 Per Use the	SUREAU OF LAND MANAGEMENT NOTICES AND REPORTS On the state of the sta	N WELLS	5 Lease Senal No. NM0202771A 6 If Indian, Allottee or Tribe Name
abandoned well ruse Form 3160-3 (APD) for such proposals. JUBNIT IN-TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No NM 061P3587C427
1 Type of Well 2 Name of Operator Novy Oil & C 3a Address 125 N. Market, Suite 1230, Wi 4. Location of Well (Footage, Sec. Unit Letter "G" 1980' FNL &	3b. Phone No. 316-265-4	2 499 7 o. (include area code) 1651	8. Well Name and No. Government C Com #1 9 API Well No. 30-025-23737 10. Field and Pool, or Exploratory Area Vada Pena por 11. County or Parish, State Lea Co., NM
12. CHECK A	PPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, I	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report ✓ Final Abandonment Notice	Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal		
following completion of the in testing has been completed. Findetermined that the site is ready oli-23-08 Rigged up remisions or 2282 feet of 5 1/2 1-26-08 TIH with tubing signarian 1-31-08 TIH with 8 5/8 paragraph 2-4-08 rig up cement true 2-5-08 couldn't tag cemen pump 225 sx cement with 2-6-08 Could not release proof with tubing. 2-7-08 Cut 8 5/8 casing co 2-8-08 started filling 8 5/8	volved operations. If the operation results in a multiplication and Abandonment Notices shall be filed only after a y for final inspection) oved casing head gasing fell 5 ft. run spear a casing split collar and dropped 60 joints of tubing incker and set at 2231 ks and mix and pump 500 sx cement 0 press at set packer at 2231 mix and pump 225 sx ce cacl pressure to 80 psi.	tiple completion or recompletion all requirements, including reclar and pulled casing it had part in the hole spent the next 6 dure ement with cacl pressure to 2 and 300 ft of cement in tubin 11 3/4 and 8 5/8 ending press 8 5/8 casing welded a plate of	ed in two places finally pulled a total of 70 ays fishing tubing out of the hole 250 psi dropped to 0 wait 2 hrs and mix and ag cut tubing at 1913 and spot 25 sx plug and sure was 280 psi. TIH with tbg to 1800 ft
14 Thereby certify that the fore Name (Printed/Typed) Michael E. Novy	,	Title Vice President	
Signature Muchus	1811 fres	Date 2 - 15 -	25 - DEPORT
	THIS SPACE FOR FEDERAL	OR STATE OFFICE	ASSEPTED FUR RECORD
certify that the applicant holds legation which would entitle the applicant t	attached Approval of this notice does not warrand or equitable title to those rights in the subject less o conduct operations thereon. le 43 USC. Section 1212, make it a crime for any	ase Office	Date MAR 4 2008 to make to any department on assess ACEARDINE
States any false, fictitious or fraudu	lent statements or representations as to any matter	within its jurisdiction.	BUREAU OF LAND WIRM AGENT

(Instructions on page 2)