

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVAL
OMB No. 1004-0125
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or re enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
ROBERT H. FORREST, JR

3a. Address
601 ELORA DR, CARLSBAD, NM 88220

4. Location of Well (Footage, Sec. T, R, M, OR Survey Description)
1650' FNL 330' FEL SEC 22, T24S, R36E, LTR. H

3b. Phone No. (include area code)
505 885-870

5. Lease Serial No
NHLE-032451-C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No
MYERS FEDERAL #1

9. API Well No.
30-025-09604

10. Field and Pool, or Exploratory Area
Kimat Tan-Yates 7 Rivers

11. County or Parish, State
LEA CO, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attachment. Overseen by Patricia Hutchins
Well was plugged on 1/10/08

RECEIVED

MAR 25 2008

HOBBS OCD

ACCEPTED FOR RECORD

MAR 22 2008

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

ROBERT H. FORREST, JR

Title OWNER / OPERATOR

Signature

Date January 30, 2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Christine Williams

OCD DISTRICT SUPERVISOR

GENERAL MANAGER

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United

MAYO MARES CASINO PILLING INC.

Company: ROBERT FORREST
 Lease: MYERS FEDERAL #
 Project: P&A
 ATTN: BOBBY FORREST
 RRC #
 CALL

FAX #
 PUSHER - GALAN JENNINGS
 BID = \$0.00
 Tracking # 07-5658-4

12/27/07 13 HRS
 SAFETY MEETING - MI RU - OPEN UP WELL - ND WELLHEAD - NH BOP - WELL HAS 2 3/8"
 TUBING IN WELL - SDFD

12/28/07 11 HRS
 SAFETY MEETING - WORK TUBING - TUBING STUCK - RIH WITH WIRELINE TO 3330' - NO
 TAG - POCH - PUMP FRESH WATER DOWN TUBING AND BACKSIDE - SDFD

01/02/08 11 HRS
 SAFETY MEETING - ROTARY RIH FREE POINT AND CUT TUBING - POH WITH 3235' OF
 TUBING - HAD TWO MISS FIRES WITH CIEP - SDFD

01/03/08 11 HRS
 SAFETY MEETING - RIH TO 3030' - CIRCULATE PLUGGING MUD - SPOT 30 SACKS @ 3030' -
 POH - WOC - SDFD

01/04/08 11 HRS
 SAFETY MEETING - TAG TOC @ 2691' - POH - RIH WITH PACKER TEST CASING - LEAKS - RIH
 AND PERF @ 1480' - POH - RIH WITH PACKER - PUMP 40 SACKS IN AND OUT OF CASING -
 POH - WOC - SDFD

01/08/08 9 HRS
 SAFETY MEETING - RIH TO TAG - NO TAG - POH - RIH WITH PACKER - TEST TO 800# - CALL
 BLM - REQUIRE REPERF - RIH AND PERF @ 1480' - TEST TO 1000# - SPOT 25 SACKS FROM
 1530' TO 1290' - POH - WOC - SDFD - SDFD

01/09/08 9 HRS
 SAFETY MEETING - RIH - NO TAG - PUMP 25 SACKS @ 1440' - POH - WOC - RIH AND TAG @
 1185' - POH - RIH AND PERF @ 340' - RIH WITH PACKER PUMP 40 SACKS FROM 240' TO 340' -
 POH - WOC - SDFD

01/10/08 12 HRS
 SAFETY MEETING - RIH AND TAG @ 325' - POH - RIH WITH PACKER - RESQUEEZE 40 SACKS
 - POH - WOC - RIH AND TAG @ 225' - LA/DOWN TUBING - DIG OUT CELLAR - CUT OFF
 WELLHEAD - SDFD

01/11/08 12 HRS
 SAFETY MEETING - SPOT 22 SACKS FROM 65' TO SURFACE IN AND OUT OF CASING - RIG DOWN - INSTALL DRY HOLE
 MARKER - FILL IN CELLAR - CUT OFF ANCHORS - MOVE OUT EQUIPMENT