Sabmit 3 Copies To Appropriate District Office	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-10	
District I 1625 N. French Dr., Hebbs, NM 88240			May 27, 200	4
1625 N French Dr , Hobbs, NM 88240 District II			30-025-11906	
1301 W Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease	
District III			STATE STATE	
1000 Rio Brazos Rd , Aztec, NM 87410	Aztec, NM Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
District IV			B-229	
1220 S. St Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well ☑ Gas Well □ Other 2. Name of Operator LEGACY RESERVES OPERATING LP		Name		
			ARNOTT RAMSAY F	i
		8. Well Number 8		
		9. OGRID Number 240974	_	
3. Address of Operator P.O. BOX 10848		10. Pool name or Wildcat		
MIDLAND, TX 79702		JUSTIS FUSSELMAN		
4. Well Location			/	_
Unit Letter A : 3		H line and	<u>330</u> feet from the <u>East</u> line.	
Section 36		ange R37E	NMPM LEA County	
	11. Elevation (Show whether	DR, RKB, RT, GR,	etc.)	
Pit or Below-grade Tank Application	3047' GL	- M8		<u></u>
Pit typeDepth to Groun	dwater Distance from neares	t fresh water well	Distance from nearest surface	
water				
Pit Liner Thickness:	mil Below-Grade Tank: Volume		bls: Construction Material	
12 Chock Ap	propriato Poy to Indicato N	latura of Nation		
12. Check Ap	propriate Box to Indicate N	lature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			K 🛛 🛛 ALTERING CASING 🗌	
		COMMENCE DRIL		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB []	
OTHER:		OTHER:	П	
13. Describe proposed or con	mpleted operations. (Clearly sta	ate all pertinent det	ails, and give pertinent dates, including	_
estimated date of starting	any proposed work). SEE RUI	LE 1103. For Multi	ple Completions: Attach wellbore	
diagram of proposed com	ipletion or recompletion.		RECEMED	
			MAD 0 ~ 0000	
- SEE ATTACHED DETA	ıL -		MAR 2 7 2008	
			LARR non	
			·	
I hereby certify that the informatio pit or below-grade tank has been/will be	n above is true and complete to e constructed or closed according to	the best of my kno	wiedge and belief. I further certify that any	1
alternative OCD-approved plan	to structed of closed according to		, a general permit 📋 or an (attached)	
signature_/ (end h'u				
SIGNATURE_/(ert N U	TITLE: SENIOR PE	ROLEUM ENGIN	<u>JEER</u> DATE <u>3/26/2008</u>	
Type or print name KENT WIL	LIAMS E-mail address: kwill	liams@legacvlp.co	m Telephone No. (432)689-5200	
For State Use Only		0.000,000		
APPROVED 1, A				
BY:	UAL LASTRICT S	INFRAME AD ACCURA		
	TITIE	JPERVISOR/CENER	ALMANAGER _ APR 2 9 2002	
Conditions of Approval (if any):	comTITLE		al managep date R 2 9 2008	

.

.

Legacy Reserves DAILY OPERATIONS REPORT

Ramsay Arnott F # 8

Page 1 of 1

Ramsay Arnott F #8

Field: Justis Fusselman

Acidize Well.

Aug 24, 2007Friday(Day 1)MIRU Key Pulling Unit. Secure Well. SDFWE

Aug 27, 2007 Monday (Day 2) OWU. Unhang well. Unseat pump. POOH w/102 - .875 rods (hang in derrick). Laid down 9 - .875" rods and 157 - .750" rods and 20' pump. ND wellhead, NU BOP's. Release 5-1/2" TAC. RIH w/4 jts. 2-3/8" tbg, tag PBTD 6861'. POOH w/212 jts. 2-3/8" tubing and 4 additional joints that we picked up. Lay down TAC and SN. PU 5-1/2" casing scraper and blade bit. Ran 2 flappers, then 14 stands of 2-3/8", bailer and 4' sub. RIH w/90 stands on 2-3/8". Secure Well. SDFN.

Aug 28, 2007 Tuesday (Day 3)

OWU. FIH w/2-3/8" production tubing. Tag PBTD @ 6870' by tubing tally. Tagged solid bottom. RU power tongs, tried to rotate on PBTD, blade bit jumping. Called PBTD @ 6870'. POOH w/2-3/8" tbg, bailer, scraper and bit. RU Capitan Wireline Services. RIH w/GRN-CNL tool. Tagged PBTD @ 6856' wireline measurements. Contacted Midland Office, they said it was OK to continue with workover procedure. RU tubing testers. Pick up 5-1/2" watson packer and SN. Test tubing in hole to 5000 psig. Left packer swinging @ 6700'. Secure Well. SDFN.

Aug 29, 2007 Wednesday (Day 4)

OWU. RU Rising Star and Brine Transports. Pump 125 BBLS of 2% KCL, did not circulate. Spot 250 gals. of 15% NEFE acid (bottom of packer @ 6860'). Displaced spot to the end of tubing. POOH to 6691' and set packer. Load casing with 19 BBLS of 2% KCL. Test casing to 500 psig. Monitored casing pressure during acid job. Started pumping acid, initial rate 4.5 BPM @ 1270 psig. Pump 3000 gals. 15% NEFE acid in 3 stages w/2 salt blocks. 1st salt block 500 lbs had 250 psig. increase in pressure. 2nd salt block 1000 lbs salt pressure climbed to 3820 psig and broke back. Flushed job w/ 100 bbls 2% KCL water. Went on vacuum. RDMO Rising Star. Release packer and POOH w/tbg and packer. RIH w/ SN, 1 jt. Of 2-3/8" Enduralloy tbg, 3 jts. 2-3/8" tbg, 5-1/2" TAC, and 210 jts. 2-3/8" tbg. ND BOP's, NU Wellhead. Set TAC w/12000 lbs. TOTAL LOAD FOR ACID JOB 327 BW. Secure Well. SDFN.

Aug 30, 2007 Thursday (Day 5) OWU. Unload fiberglass rods and K-bars. PU 2" X 1.5" X 24' pump, RIH w/ 1- 1-1/2" Kbar, 21K shear tool, 5 -1-1/2" Kbars, 103 - 7/8" steel rods, 107 - 1" fiberglass rods, 18' FG pony rod, and 21' polish rod. Seat pump. Load tbg. Space out pump. Waiting on electrician to re-sheave motor and PU crew to balance unit. TOTAL LOAD JOB 372 BW. RDMOPU.

Aug 31, 2007 Friday (Day 6) Electrician changed sheave to 11 SPM. Got Pumping Unit Service to rebalance unit to fiberglass rods. Start Well

pumping to test. Final Report.