Submit 3 Copies To Appropriate District State of New Mexico	
Office State of New Mexico,	Form C-103
Energy, Minerals and Natural Resources	May 27, 2004
District I 1625 N French Dr. Holps IN 18340 District II 1201 W Constant And Natural Resources District II	30-025-28514
1301 w Grand Ave, Artesia, NM 88210 OTE CONSERVITION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE S FEE
1000 Rio Brazos Rd, Aztec, APR 310, 2008 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr. Santa Ee, NM	
87505 SIDE REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Ecuse Manie of Onit Agreement Mane
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State A A/C 1
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other Water Injection Well	8. Well Number 119
2. Name of Operator	9. OGRID Number
Petrohawk Operating	194099
3. Address of Operator	10. Pool name or Wildcat
1000 Louisiana, Suite 5600 Houston TX 77002	LanglieMattix SR-Q-GB
4. Well Location	ـــــــــــــــــــــــــــــــــــــ
Unit Letter P : 1295 feet from the South line and	1295 feet from the East line
Section 3 Township 23S Range 36E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
GR-3461'	
Pit or Below-grade Tank Application 🗌 or Closure 🗌	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDist	ance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORI	— — — —
	— — —
	JOB []
OTHER: DTHER: TA	status Test 🛛
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
Test Date: 4-28-08	
1. Load csg w/ 2% KCL. (Pkr @ 3546')	·
2. Prossure test and surface to 2546' to 560 noi for 20 minutes. (See attached short)	
2. Pressure test csg surface to 3546' to 560 psi for 30 minutes. (See attached chart)	
3. Request TA status for 5 years.	
The Americal of Temporary / /	
This Approval of Temporary Abandonment Expires	
Abandonment Expires	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].	
SIGNATURE Onl Size TITLE Production Foreman	
	nDATE_4-28-08
Type or print name Joel Sisk E-mail address: jsisk@petrohawk.com	Telephone No. 575-394-2574
For State Use Only	
APPROVED BY Mina William OC DISTINCT SUPERVISOR/GEN	FRAI MASHARON MAY 0 7 2002
	DATE DATE LUUU
Conditions of Approval (if any):	,

