



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

**\*Response Required – Deadline Enclosed\***

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

08-May-08

**MANHATTAN PETROLEUM INC**

PO BOX 35888

TULSA OK 74153

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***


STATE 32 No.001					B-32-9S-38E	30-025-24592-00-00	
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/07/2008	Plugged Well	Surface Restor	Maxey Brown	Yes	No	8/10/2008	iMGB0812926168
Comments on Inspection:		DO NOT RELEASE. RULE 202. NEED TO REMOVE VALVES AND RISER AT WELLHEAD. ALSO NEED TO REMOVE CONDUIT AND ELECTRIC CONTROL PANEL FROM WEST SIDE OF LOCATION. THIS IS 1ST LETTER OF NON-COMPLIANCE.					

MARTIN No.001					N-9-9S-38E	30-025-24882-00-00	
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/07/2008	Plugged Well	Surface Restor	Maxey Brown	Yes	No	8/10/2008	iMGB0812925960
Comments on Inspection:		DO NOT RELEASE. RULE 202. NEED TO REMOVE VALVES FROM WELLHEAD. THIS IS 1ST LETTER OF NON-COMPLIANCE.					

DAVENPORT No.001					H-17-9S-38E	30-025-24995-00-00	
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/07/2008	Plugged Well	Surface Restor	Maxey Brown	Yes	No	8/10/2008	iMGB0812925298
Comments on Inspection:		DO NOT RELEASE. RULE 202. NEED TO REMOVE VALVES FROM WELLHEAD, ALSO REMOVE ELECTRIC CONTROL PANEL AND CONDUIT FROM SOUTHWEST CORNER OF LOCATION THIS IS 1ST LETTER OF NON-COMPLIANCE.					

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Hobbs OCD District Office

**COMPLIANCE OFFICER**

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER  
014H15215335  
\$0.410  
05/08/2008  
Mailed From 88240  
US POSTAGE

MANHATTAN PETROLEUM INC  
PO BOX 35888  
TULSA OK 74153