Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103		
Office District I	Energy, Minerals and Natu	ral Resources	May 27, 2004		
1625 N French Dr , Hobbs, NM 88240			WELL API NO.		
District II 1301 W Grand Ave, Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-06586		
District III	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease		
1000 Rio Brazos Rd, Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.		
1220 S St Francis Dr , Santa Fe, NM	2 5 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		o. State On & Gas Lease No.		
87505					
	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CTATE C		
PROPOSALS)			STATE S 8. Well Number 1		
1. Type of Well: Oil Well	Gas Well Other				
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Number 4323		
3. Address of Operator	D. () C		10. Pool name or Wildcat		
15 SMITH ROAD, MIDLAND, T	EXAS 79705		PENROSE SKELLY GRAYBURG		
4. Well Location					
Unit Letter D 660 feet	from the NORTH line and 660 fee	et from the WEST li	ine /		
Section 15 Towns			County LEA		
		RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application O	or Closure 🗌				
Pit typeDepth to Groundw	aterDistance from nearest fresh w	ater well Dista	ance from nearest surface water		
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Con	nstruction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	ITENTION TO:	SUBS	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB		
OTHER ACIDIZE & PPI SCALE	SQUEEZE	OTHER:			
13. Describe proposed or comp	leted operations. (Clearly state all p	pertinent details, and	give pertinent dates, including estimated date		
of starting any proposed we	ork). SEE RULE 1103. For Multipl	le Completions: Att	ach wellbore diagram of proposed completion		
or recompletion.					
CHEVRON U.S.A. INC. INTENDS	TO ACIDIZE & SCALE SQUEEZ	E THE SUBJECT V	WELL.		
THE INTENDED PROCEDURE A	ND WELLBORE DIAGRAM IS A	TTACHED FOR YO	OUR APPROVAL.		
Lhereby certify that the information	above is true and complete to the he	agt of may lemosylados	and balleform and a second second		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.					
$\lambda = \lambda + \lambda + \lambda = \lambda + \lambda = \lambda = \lambda = \lambda = \lambda = $					
SIGNATURE MISEL Y	TITLE Res	gulatory Specialist	DATE 05-05-2008		
Type or print name Denise Pinkert For State Use Only	on E-mail address: <u>leakejd@ch</u>	nevron.com	Telephone No. 432-687-7375		
	OE	TDOLEHRA ENION	NEER MAY 7 5 2000		
APPROVED BY:	TITLE	TROLEUM ENGIN	DATE		
Conditions of Approval (if any):			······		



MAY n 7 2009



State S #1
API #30-025-06586
660' FNL & 660' FWL
T21S, R37E, Section 15
Lea County, NM
Penrose Skelly
Job: Acidize and PPI Scale Squeeze

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 5/027/2008. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 3. MI & RU workover unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. POH and LD rods ND WH & NU BOP. Release TAC and POH w/ 2-7/8" tubing. LD tubing if pitting and corrosion is evident.
- 4. PU and GIH with 4 ¾" MT bit, and 2-7/8" work string to 4050'. Reverse circulate well clean from 4050' using 8.6 PPG cut brine water, and foam-air unit if necessary. POH with tbg string and bit. LD bit.
- 5. RIH w/ 5-1/2" PPI packer w/ SCV and 12' element spacing. Test 2-7/8" workstring to 4000 psi while RIH. Test PPI packer in blank pipe. Mark Settings.
- 6. MI & RU DS Services. Acidize perfs 3698'-3958' with 4,500 gal 15% NEFE HCl acid* at a maximum rate of **1 BPM** and a maximum surface pressure of **4000 psi** as follows:

Well: State S #1

Location:

State:

KB:

Elevations

660' FNL & 660' FW L, Sec 15, T-21S, R-37E

Field: Penrose Skelly County: Lea, NM

NM

3452


Current

Wellbore Diagram

Formation: Grayburg

Well Info:

6/25/1948 Comp. Date: Spud Date: 8/26/1948 API: 30-025-06586 RefNO: FA7691





Size: 13-3/8", 36#, ERW Set: @ 293' w/ 300 sks 17-1/4" Yes Surface (circ)

sing

		Hole Size: Circ:	
		Intermediate Ca	sing
·		Size:	8-5/8", 32#, SS
L			2797' w/ 1200 sks
L		Hole Size:	
ı	1	Circ:	
1		TOC:	Surface (calc)
_	.		
ı			
1	.		
ı			
l		Perfs	Status
-	‡ 	3698-3705'	Grayburg - Open
Ť	† 	3713-16'	Grayburg - Open
ż	‡ ‡	3724-33'	Grayburg - Open
÷	† 	3763-71'	Grayburg - Open
	1 1 1 1	3774-82'	Grayburg - Open
÷	± ±=	3787-961	Grayburg - Open
÷	Ŧ 	3817-28'	Grayburg - Open
÷	± ±±	3837-59'	Grayburg - Open
÷	Ŧ !! ;	3865-70'	Grayburg - Open
1	4 i l 11	3876-99'	Grayburg - Open
÷	± 	3912-22'	Grayburg - Open
L	I II	3940-45'	Grayburg - Open
14.	<u>† </u>	3952-58'	Grayburg - Open
T	T II T		, , ,
ı			
1	00		
l	$I \cup I \cup I$		
ı	1 11		
1	1 1		
ı] []		
	1 1		
	7 × 12 × 7 × 1. × 1		
ŀ			
1		Perfs	Status
<u>l.</u>			Status
1		6504'	Drinkard - Cmt Sqzd
1		6507'	Drinkard - Cmt Sqzd
Į.		6510'	Drinkard - Cmt Sqzd
L	10	6514'	Drinkard - Cmt Sqzd
i		6519'	Drinkard - Cmt Sqzd
Ī		6527'	Drinkard - Cmt Sqzd
1:	44		
ī.		6560'-6600'	Drinkard - Cmt Sqzd
		6625'-6660'	Drinkard OH - Below Sand Plug
		Production Casi	-
		Size:	5-1/2", 15 5, J-55
1.	12 to 11		6625' w/ 400 sks
Z		Hole Size:	7-7/8"
٦	· · · · · · · · · · · · · · · · · · ·	Circ:	No
	10 to	TOC:	3100' (CBL)
	San the San		

CICR @ 6444' (20' cmt on top)

Updated: 17-Apr-08

COTD: 6434' PBTD: 6434' TD: 6660'

By: rjdg