(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR USE "APPLIT PROPOSALS")	State of New Me Energy, Minerals and Natu OIL CONSERVATION 1220 South St. Fran Santa Fe, NM 87  TICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLA ICATION FOR PERMIT" (FORM C-101) FOR	WELL A 30-025-3 5. Indica 7505 6. State 7. Lease VACUU UNIT			
Type of Well: Oil Well      Name of Operator	Gas Well Other INJECTION	8. Well	Number 149 ID Number 4323		
CHEVRON U.S.A. INC.		9. OOK	Number 4323		
3. Address of Operator 15 SMITH ROAD, MIDLAND, T	EXAS 79705		name or Wildcat M GRAYBURG SAN ANDRES		
4. Well Location					
Unit Letter C: 1330 feet from the SOUTH line and 1980 feet from the WEST line					
Section 1 Township 18-S Range 34-E NMPM County LEA  11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3997' GL					
3997' GL  Pit or Below-grade Tank Application or Closure					
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction M	laterial		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	☐ PLUG AND ABANDON ☐ REMEDIAL WOR		NT REPORT OF:  ALTERING CASING  NS. P AND A		
OTHER CLEAN OUT ADD PERE	S & ACIDIZE	OTHER:			
OTHER CLEAN OUT, ADD PERFS, & ACIDIZE  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  CHEVRON U.S.A. INC. INTENDS TO CLEAN OUT THE SUBJECT WELL TO 4900' & ADD SAN ANDRES TRNSITION PERFS & ACIDIZE. THIS WORK IS IN PREPARATION FOR THE VGSAU PHASE LA CO2 EXPANSION.  THE INTENDED PROCEDURE AND WELLBORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.					
I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Denise Pinkerto For State Use Only	closed according to NMOCD guidelines [	], a general permit 🗌 or an (attach	ed) alternative OCD-approved plan □.		
1 of State OSC Only	PETI	ROLEUM ENGINEER	MAN 7 F OCC		
APPROVED BY: Conditions of Approval (if any):	TITLE_		ATEAY 7 5 2008		



MAY 0 2 2008 HOBBS OCD

## VGSAU 149

API No. 30-025-30847 Vacuum (Grayburg San Andres) Field Lea County, NM

Procedure to: C/O Perforate and Stim T-Z

Subject well was MIT tested to 560 psi on 10/19/2007. Pressure testing the casing prior to commencing the workover is not necessary.

- 1. MIRU PU & RU. Pump 25 bbls 10# BW dn tbg, take SI pressure and calculate kill weight fluid. Kill well as nec. ND WH. NU BOP & Envirovac.
- 2. Unset pkr & POOH w/ tbg & pkr. Truck off Duoline tbg. If pkr rubber does not relax it may be nec to perf tbg above pkr prior to POOH as no On/Off tool is mentioned in well files.
- 3. TIH w/ 6-1/8" MT bit, 6 3-1/2" DC on 2-7/8" WS. D/O fill & cmt to new PBTD of 4900'. Circ clean with 10# BW. Spot 500 gal acetic acid at PBTD. POOH w/ WS, DCs & bit. NOTE: The latest maximum depth recorded with a drill bit was 4810' in November 2000. Fill was tagged at 4059' in October 2007. If casing is collapsed, POOH w/bit and GIH w/ 6-1/8" cone buster mill to C/O. If the casing still continues to "fall in" use a casing roller to swedge out the casing.
- 4. MI Baker Atlas to perforate the following intervals w/ 3-1/8" slick guns w/ 2 DP JSPF 120 phasing. Tie into Halliburton Logging Services Gamma Depth Control Log dated 3/31/1992 for depth control. A short joint is located at 4053-4071. Perf intervals are:

4601-4608, 4613-4619, 4625-4628, 4634-4641, 4651-4655, 4667-4671, 4674-4685, 4695-4710, 4723-4737, 4740-4746, 4748-4758, 4762-4771, 4775-4783, 4788-4804, 4809-4812, 4818-4826, 4828-4837, 4840-4843

- 5. TIH w/7" treating packer on 2-7/8" workstring and set at 4595'.
- 6. MIRU Halliburton to acidize the new TZ perfs 4601-4843 with 4000 gallons 15% HCL in 2 stages. Drop 1500# rock salt between stages mixed in GBW. SI 2 hrs. Flowback or swab to tank to recover load. Rate 5-6 BPM, Max press 5000 psi. If packer communicates then move uphole and acidize entire interval 4132-4843 as below.
- 7. Release packer, pull up and set at +/- 4035'.
- 8. RU Halliburton to acidize existing San Andres perfs and TZ perfs 4132-4843 with 8000 gallons 15% HCL in 4 stages. Drop 1500# rock salt between stages mixed in GBW. SI 2 hrs. Flowback or swab to tank to recover load. Rate 5-6 BPM, Max press 5000 psi.
- 9. Kill well with 10 ppg BW. Unset pkr & POOH with WS and pkr.
- 10. TIH w/ bit and C/O rock salt to PBTD of 4900'. TOH w/ WS and bit.
- 11. TIH w/ new 2-3/8" Fiberline injection tbg & pkr w/ On-Off tool. Set pkr @  $\sim$  4043' w/ 10 pt compression. Space out. Release from On-Off tool, circ hole with 10 ppg pkr fluid. Latch back onto On-Off tool & land tbg hanger. ND BOP. NU WH. Run MIT for OCD.
- 12. Hookup injection lines. Clean location. RDMO PU & RU.
- 13. Turn well over to production department.
- 14. Run injection profile.

BAS 4/29/08

## VGSAU #149 Wellbore Diagram

	dres Unit NL NM	Well # API Unit Ltr.: TSHP/Rng. Unit Ltr.: TSHP/Rng Directions CHEVNO	149 St. Lse. 857948 30-025-30847 C Section 1 S-18 E-34 Section: Buckeye, NM KX1746	
Surface Casing           Size:         13 3/8"           Wt , Grd ·         48 & 54.5#           Depth:         1550'           Sxs Cmt         1700           Circulate:         200 sx           TOC:         Surface           Hole Size:         17 1/2"           Intermediate Casing         Size           Size         9 5/8"           Wt , Grd ·         2800'           Sxs Cmt:         1570           Circulate:         245 sx           TOC         Surface           Hole Size:         7"           Wt , Grd.         26# K-55           Depth:         5000'           Sxs Cmt         950           Circulate:         135 sx           TOC         Surface           Hole Size:         8 3/4"			History   10/90 ini Completion   CO to 4810', Perf @ 2 jspf at 4454'-68', 4502'-07', 4581'-90' (56 holes) Acid w / 4300 gis 15% NEFE RBP @ 4440 Perf @ 2 jspf at 4292'-4304', 4360'-64', 4376'-81', 4411'-24' Acidize w / 4300 gis 15% NEFE RBP @ 4275 Perf @ 2 jspf 4132'-40', 4216'-20', 4226'-34', 4247'-58' Acidize w / 4300 gis 15% NEFE IP @ 270 862w 15g   3/92 Add Perfs, Acid, Convert to WiW CO to 4810' Perf 2 jspf @ 4262'-66', 4305'-21', 27'-32' 37'-41' 86'-88', 4428'-32', 72'-75', 86'-88', 97'-99', 4513'-20', 34'-36', 48'-53', 59'-61', 68'-70', 72'-78', 4601'-08', 13'-19', 51'-55', 67'-71', 79'-85', 95'-98' Spot 1100 gis of 20% NEFE HCI Acid perfs w/ 8500 gis NEFE HCI, 4000# RS, 304 BS's, & 50 bbis gelled brine in 4 stgs 11/00 CO, Perf, Acidize Tag fill @ 4065', CO to 4810' w/ bit, Perf 2 jspf 4268-71, 4344-56, 4496-4500, 22-32, 39-46, 63-66, 73-78, 4625-28, 34-41, 74-79, 4698-4710 Spot 1000 gal 20% NEFE & 5000# RS in 5 stgs 10/07 Tagged fill @ 4059' Injection @ 1000 bwpd	
128 jts 2 7/8" Duoline tbg to 4031'  Loc-Set Pkr @ 4036'  Fill @ 4059'  Perfs @ 4132'-4710'				
PBTD: 4,810 TD. 5,000				

## Chevron U.S.A. Inc. Wellbore Diagram: VGSAU 149

