a de la companya de la	• *
Submit 3 Copies To Appropriate District a State of Nev	v Mexico Form C-103
District I	Natural Resources May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II	00 005 11040 6
District II 1301 W. Grand Ave., Artesia, NM SAPR 28 2000 1220 South St District III	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, Martin DC Stitta Fe, N District IV	
1220 S. St. Francis Dr., Santa Francis 2000	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM PROPOSALS.)	PEN OR PLUG BACK TO A Myong Langlio Mattix Unit
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other 2. Name of Operator	236 9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250 4. Well Location	Langlie Mattix 7Rvr Qn-GB 2
	south line and 1980 feet from the east line
Section 7 Township 245	
	ther DR, RKB, RT, GR, etc.) 3310'
Pit or Below-grade Tank Application	
Bit type <u>Steel</u> Depth to Groundwater <u>100'</u> Distance from neares	t fresh water well N/A . Distance from nearest surface water N/A
A1 (A	lumebbls; Construction Material
12. Check Appropriate Box to Indi	cate _l Nature of Notice, Report, or Other Data
	-
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND CASING TEST AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completion	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Multiple 1103.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Mu or recompletion. TD-3585' PBTD-3298' 9-5/8" 36# csg @ 1205' 7" 20# csg @ 3419' w/20 Thank Image: Completed operations. I. RIH & Tag Cmt/CIBP @ 32. Perf @ 2895' sqz 50sx	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: Image: Completion of proposed completion 0H-3419-3585' CIBP-3333' w/400sx, 12-1/4" hole, T0C-Surf-Circ 0sx, 8-3/4" hole, T0C-2086'-Calc 3298' cmt to 2795' WOC-Tag cmt to Surface THE OIL CONSERVATION DIVISION MUST
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Mu or recompletion. There Image: Completed operations.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB D OTHER: Image: Completion of the proposed completion 0H-3419-3585' CIBP-3333' w/400sx, 12-1/4" hole, T0C-Surf-Circ 00sx, 8-3/4" hole, T0C-2086'-Calc 8298' cmt to 2795' WOC-Tag cmt to Surface THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting as o	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DI OTHER: OTHER: OTHER: Il pertinent details, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of proposed completion 0H-3419-3585' CIBP-3333' w/400sx, 12-1/4" hole, T0C-Surf-Circ 00sx, 8-3/4" hole, T0C-2086'-Calc 3298' cmt to 2795' WOC-Tag cmt to 1155' WOC-Tag cmt to Surface THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS the best of my knowledge and belief. I further certify that any nit or below-
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrest Image: Clearly state as of starting as o	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DLUG AND ABANDONMENT OTHER: Image: Completion of the second seco
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Image: Completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Mu or recompletion. Torrecompletion. TD-3585' PBTD-3298' 9-5/8" 36# csg @ 1205' 7" 20# csg @ 3419' w/20 1. RIH & Tag Cmt/CIBP @ 3 2. Perf @ 2895' sqz 50sx 3. Perf @ 1255' sqz 50sx 4. Perf @ 150', sqz 70sx 10# MLF between plug	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: Image: Completion of the state of the stat

- --

ī

OXY USA WTP LP Myers Langlie Mattix Unit #236 API No. 30-025-11040

7/98-CIBP @ 3333' w/ 35' cmt

0 1



12-1/4" hole @ 1205' 9-5/8" csg @ 1205' w/ 400sx-TOC-Surf-Circ

8-1/4" hole @ 3419' 7" csg @ 3419' w/ 200sx-TOC-2086'-Calc

OH @ 3419-3585'

OXY USA WTP LP - Proposed Myers Langlie Mattix Unit #236 API No. 30-025-11040

