

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ROBERT H. FORREST, JR

3a. Address

609 ELORA DR, CARLSBAD, NM 88220

3b. Phone No. (include area code)

505 8856870

4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)

1650' FNL & 330' FEL SEC 22, T24S, R36E, LTR. H

5. Lease Serial No.

NMLC-032451-C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

MYERS FEDERAL #1

9. API Well No.

30-025-09604

10. Field and Pool, or Exploratory Area

Almat Tan-Yates - 7 Rivers

11. County or Parish, State

LEA CO., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	_____
<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	_____

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attachment. Overseen by Patricia Hutchins
Well was plugged on 1/10/08.

RECEIVED

FEB 21 2008

HOBBS OCD

ACCEPTED FOR RECORD

FEB 17 2008

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

ROBERT H. FORREST, JR

Title

OWNER / OPERATOR

Signature

Robert H. Forrest Jr

Date

January 30, 2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Chris Williams

OC DISTRICT SUPERVISOR / GENERAL MANAGER

Date

MAY 21 2008

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

MAYO MARRS CASING PULLING INC.

Company. ROBERT FORREST
Lease MYERS FEDERAL # 1
Project: P&A
ATTN: BOBBY FORREST
RRC #.
CALL

FAX #
PUSHER - GALAN JENNINGS
BID = \$0.00
Tracking # 07-5698-4

12/27/07 13 HRS
SAFETY MEETING - MI RU - OPEN UP WELL - ND WELLHEAD - NU BOP - WELL HAS 2 3/8"
TUBING IN WELL - SDFD

12/28/07 11 HRS
SAFETY MEETING - WORK TUBING - TUBING STUCK - RIH WITH WIRELINE TO 3330' - NO
TAG - POOH - PUMP FRESH WATER DOWN TUBING AND BACKSIDE - SDFD

01/02/08 11 HRS
SAFETY MEETING - ROTARY RIH FREE POINT AND CUT TUBING - POH WITH 3235' OF
TUBING - HAD TWO MISS FIRES WITH CIBP - SDFD

01/03/08 11 HRS
SAFETY MEETING - RIH TO 3030' - CIRCULATE PLUGGING MUD - SPOT 30 SACKS @ 3030' -
POH - WOC - SDFD

01/04/08 11 HRS
SAFETY MEETING - TAG TOC @ 2691' - POH - RIH WITH PACKER TEST CASING - LEAKS - RIH
AND PERF @ 1480' - POH - RIH WITH PACKER - PUMP 40 SACKS IN AND OUT OF CASING -
POH - WOC - SDFD

01/08/08 9 HRS
SAFETY MEETING - RIH TO TAG - NO TAG - POH - RIH WITH PACKER - TEST TO 800# - CALL
BLM - REQUIRE REPERF - RIH AND PERF @ 1480' - TEST TO 1000# - SPOT 25 SACKS FROM
1530' TO 1290' - POH - WOC - SDFD - SDFD

01/09/08 9 HRS
SAFETY MEETING - RIH - NO TAG - PUMP 25 SACKS @ 1440' - POH - WOC - RIH AND TAG @
1185' - POH - RIH AND PERF @ 340' - RIH WITH PACKER PUMP 40 SACKS FROM 240' TO 340' -
POH - WOC - SDFD

01/10/08 12 HRS
SAFETY MEETING - RIH AND TAG @ 325' - POH - RIH WITH PACKER - RESQUEEZE 40 SACKS
- POH - WOC - RIH AND TAG @ 229' - LAYDOWN TUBING - DIG OUT CELLAR - CUT OFF
WELLHEAD - SDFD

01/11/08 12 HRS
SAFETY MEETING - SPOT 22 SACKS FROM 65' TO SURFACE IN AND OUT OF CASING - RIG DOWN - INSTALL DRY HOLE
MARKER - FILL IN CELLAR - CUT OFF ANCHORS - MOVE OUT EQUIPMENT