Office State of New Mexico	Form C-103
District 1 1625 N. French Dr., Hold Add Control of Cont	May 27, 2004
	30-005-20687
	5: Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 1410 / ZUUM 1220 South St. Francis Dr.	STATE XX AFEE
District IV 1220 S St Francis Dresha FAMBES OCD 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Tom State "36"
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD	8. Well Number 2 _
2. Name of Operator John R. Stearns dba Stearns	9. OGRID Number 21566
3. Address of Operator	10. Pool name or Wildcat
HC 65 Box 988, Crossroads, New Mexico	SWD San Andres
4. Well Location	
Unit Letter H : 1980 feet from the North line and 660	_feet from the _East line
	aves County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	and the second
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDist	ance from nearest surface water
	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
COMMENCE DRI	
PULL OR ALTER CASING	JOB
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att 	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 	ach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown POH to 2225', pumped 25 sx
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH with 2.5 gelled brine. POH with tbg. Tag approved by Maxie 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement. circ. To surface. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH with 20.5 and 20	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement. circ. To surface. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5' 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5' gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.54 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement. circ. To surface. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.54 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] o SIGNATURE SIGNATURE Type or print name John R. Stearns For State Use Only 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wit @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. N 5/05/08Rig down pulling unit, clean location and install dry hole marker. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or SIGNATURE	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.54 gelled brine. POH with tbg. Tag approved by Maxie 5/01/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08—Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or SIGNATURE	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat cement, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 dlass C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 dlass C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 dlass C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. To surface. POH with 20.5 the start of the star	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 4/28/08—MIRU J & B Well Servicing. ND Well head, NU BOP. RIH with 2-3/8" tbg. POH with 20 jts.tbg. SD, WOC. Tag approved by Maxie Brown. 4/29/08—RIH with tbg., tagged TOC @ 3735', circ. 9.5 gelled brine. Tag witnessed by class C neat, POH 20 jts tbg. SD, WOC. RIH, tagged TOC @ 1946'. Circ. With 9.5 4/30/08—RIH with tbg. to 1820', pumped 75 sx class C neat, braden head circ. POH wi @ 1511', circ. With 9.5# gelled brine. POH with tbg. Tag approved by Maxie 5/01/08Circ 5-1/2" & 8*5/8" csg. with 310 sx class C neat, circ. To surface. V 5/05/08Rig down pulling unit, clean location and install dry hole marker. 	ach wellbore diagram of proposed completion to 3838', pump 35 sx class C neat cement Maxie Brown. POH to 2225', pumped 25 sx i# gelled brine. POH with 10 jts. SDON. th tbg. SD< WOC.RIH with tbg, tagged TOC e Brown. SDON. Vitnessed by Maxie Briwn. SDON.