Form 3160-5 UNITED STATES (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			OCD-H(	OBBS FORM APPROVED OMB NO 1004-0137 Expires July 31, 2010 5 Lease Serial No	
SUNDRY NOTICES AND REPORTS ON WELLS			NMNM0631		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe Nar	ne
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No	
1. Type of Well       X       Oil Well       Gas Well       Other				8. Well Name and No. Federal 11-20-34	
Samson Resources Company			No. 3		
3a. Address   3b. Phone No (include area code)			ea code)	9 API Well No 30-025-30424	
200 N. Loraine St., Ste 1010; Midland, TX 79701         (432) 683-7063           4. Location of Well (Footage, Sec., T, R, M., or Survey Description)         (432) 683-7063			10 Field and Pool, or Explorato	ry Area	
1890' FSL & 660' FWL Sec. 11-20S-34E				Lea; Bone Springs /	
UnitL				Lea N	М
12. CHECK APPROPRIATE	E BOX(ES) TO INDIC	CATE NATURE OF N	IOTICE, REPC		<u></u>
TYPE OF SUBMISSION			<u></u>		
X Notice of Intent	Acidıze	Deepen	Production	n (Start/Resume) Water Shut-C	)ff
Subsequent Report	Alter Casing	Fracture Treat	Reclamation Recomple		Perf
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporari	ily Abandon <u>Third Bone</u> posal	Spring
<ol> <li>Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. It testing has been completed Final Abandonment M determined that the final site is ready for final inspect</li> <li>POH W/rods and pump. Rls Tac 2. Load hole. POH w/tubing.</li> <li>GIH w/bit and scraper on 2 3/ 4. Clean out to 11000'. POH. R 5. Perf Third Bone Spring (10860)</li> </ol>	rtical depths of all pertinent market subsequent reports shall be filed wa	rs and zones ithin 30 days be filed once operator has			
<ol> <li>GIH w/retrv pkr. Set pkr @ 1</li> <li>Breakdown perfs. Acdz. Swab</li> <li>Frac. Flow back. RU slickli</li> </ol>	back load. ne. Set blanking	plug in o/o tool	l. Test to	500 psi:	
9. ND frac valves. NU BOP. Rls o/o tool. POH LD frac string. 10. GIH w/tubing. Latch o/o tool. ND BOP. NU tree. 11. RU slickline. Retrieve blanking plug. 12. Flow test.				APPROVED	
No H2S ********Please Expedite - Rig Availability********				JAMES A. AMOS SUPERVISOR-EE	] 5
14 Thereby certify that the foregoing is true and correct Name (Printed/Typed) Kenny Krayfietz	0	Title Distri	ct Engineer	、	
Signature Manuer Milleult Date 4/21/2008					
	S SPACE FOR FEDE	RAL OR STATE OF	FICE USE		
Approved by	OC DESTRIC	Title		Date	
Conditions of approval, if any, are attached Approval of this not the applicant holds legal or equitable title to those rights in the sul entitle the applicant to conduct operations thereon	ice does not warrant or certify	that Office	<u>JEDAL AAANU</u>		
Title 18 U S C Section 1001, and Title 43 U S.C Section 1212, fictutious or fraudulent statements or representations as to any ma		1 knowingly and willfully to m	nake to any departm	nent or agency of the United States any f	alse,

ţ