Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO 1625 N French Dr , Hobbs, NM 88240 District II 30-025-33385 OIL CONSERVATION DIVISION 1301 W Grand Ave, Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE X FEE \square 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St Francis Dr , Santa Fe, NM LG-478 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Gallagher State PROPOSALS) 8. Well Number 2 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number Pecos Operating Company 246798 3. Address of Operator 10. Pool name or Wildcat 400 W. Illinois Ave., Suite 1210 Midland, TX 79701 Big Dog; Stawn S/Townsend 4. Well Location Unit Letter 2646 feet from the 2299 North line and feet from the West Section 2 Township 16-S Range 35-E Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3992' GL Pit or Below-grade Tank Application 🗌 or Closure 🔲 Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume bbls: Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON ☐ PERFORM REMEDIAL WORK □ REMEDIAL WORK ALTERING CASING □ TEMPORARILY ABANDON \Box COMMENCE DRILLING OPNS.□ CHANGE PLANS P AND A PULL OR ALTER CASING MULTIPLE COMPL П CASING/CEMENT JOB OTHER: П OTHER. Add pay/ DH Commingle 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. PODH w/ production equipment Drill out cement w/ foam air 11.550' to 11.640' Perforate Strawn 11,538'-558' and 11,566'-586' w/ 1 spf. (40 holes) Acidize Strawn perfs w/ 3000 gal 15% NEFE HCl. Run production tubing to 11,617'. Run production pump & rods. Place well on production as DH Commingled in Big Dog; Strawn, South and Townsend; Permo, Upper Penn, per OCD order DHC-4002. On production 4-23-08 8 BO, 30 BW, 36 MCFD. MAY 27 2008 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan []. **SIGNATURE** TITLE Manager DATE 5-22-08 Type or print name E-mail address: billh@pecoscompanies.com Telephone No. For State Use Only 432-620-8480 OC DESTRUCT SUPERVISOR/GENERAL MANAGES APPROVED BY:

Conditions of Approval (if any):