Form 3160-5 (September 2001)

## DEP

UNITED STATES	OCD-HOBPOM APPROVED OMB No. 1004-0135
ARTMENT OF THE INTERIOR	Expires January 31, 2004
PEAU OF LAND MANAGEMENT	5 Longo Sorral No.

BUREAU OF LAND MANAGEMENT		5 Lease Senal No.	
SUNDRY NOTICES AND REPORTS ON WELLS		NM-052	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.		7. If Unit or CA/Agreement, Name and/or No	
1. Type of Well Gas Well Other MAY 0 6 7008		NM70989X  8. Well Name and No.	
		Mescalero Ridge 13  Mescalero Ridge 13  Mescalero Ridge 13  Mescalero Ridge 13  Mescalero Ridge 13	
3a Address       3b Phone No. (include area code)         13727 Noel Rd. Ste. 500, Dallas, TX 75240       972-628-1467		10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		Pearl (Queen), Seven Rivers  11. County or Parish, State	
1980' FSL & 990' FWL; Sec 35, T-19-S, R-34-E		Lea, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent    Acidize   Deeper	Production (State Treat Reclamation Recomplete	Well Integrity Other	
Final Abandonment Notice Change Plans Plug ar  Convert to Injection Plug Ba		·	
Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1.) POOH w/ 2 3/8" tbg, PU 5 1/2" CIBP & RIH set CIBP @ 3,950'  2.) CIRC well w/ pxa mud & mix, pump 25sx cmt plug on top of CIBP @ 3,950'. POOH w/ tbg RUWL perf gun & perf sqz @ 3,435'. POOH & RDWL PU 5 1/2" pkr & RIH w/ pkr & tbg to 2,900', set pkr est inj rate - pressure up to 1200# & held. POOH w/ tbg & pkr, RIH w/ tbg to 3,485 mix & pump 50 sx cmt plug @ 3,485. POOH w/ tbg WOC. RIH w/ tbg & tag top of cmt plug @ 3,264, POOH w/ tbg, RUWL & perf gun, RIH & oerf sqz @ 1,785'. POOH & RDWL, PU pkr & RIH w/ pkr & tbg to 1500# ste pkr est inj rate & mix sqz. 35sx cmt plug @ 1,785. CWI WOC releace pkr & POOH w/ tbg & pkr. LD pkr & RIH w/ tbg tag top of cmt plug @ 1,636', POOH w/ tbg SDFN.  3.) RUWL & perf gun, perf & sqz @ 255'. POOH & RDWL pu 5 1/2" pkr & RIH w/ pkr set pkr est inj rate & mix & sqz 90sx cmt plug @255', release pkr & POOH w/ tbg & pkr, mix & spot cmt plug back to surf. Dig out & cut off wellhead 3' BGL weld on steel plate & dry hole marker.			
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	ı		
Kristin Hodge	Title Regulatory Analyst	WWW.DTED FOR BEGOVE	
Signature AUTU	Date 0	04/28/AGCEPTED FOR RECORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved of Justice Design and the second of	SUPER/SOR/GENERAL	AMAY 2 2008	
Conditions of approval, if any, are attached Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	errant or or lease Office	BUREAU OF LAND MANAGEMENT	
		THE PARTY OF LAND WITH THE WAY	