UNITED STATES OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED OM B No 1004-0135 Expires: January 31, 2004

BUREAU OF LAND MANAGEMENT				Ехриса. Јаниану 31, 2004	
				5 Lease Serial No	
MAY OF ZUMPS AND REPORTS ON WELLS				NM-052	
MAY Do not use this form for proposals to drill or to re-enter an abandoned Well Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No NM70989C	
1. Type of Well Gas Well Other					8. Well Name and No.
2. Name of Operator Merit Energy Company					Mescalero Ridge 14 9. API Well No.
3a Address 3b. Phone No. (include				de area code)	30-025-21613
13727 Noel Rd. Ste. 500, Dallas, TX 75240 972-628-			1467		10 Field and Pool, or Exploratory Area Pearl (Queen), Seven Rivers
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL & 990' FWL; Sec 35, T-19-S, R-34-E					11. County or Parish, State
000 FIL & 970 F.W.L., Sec. 33, 1-17-13, N-34-L					Lea, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE					REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
	Acidize Deepen Production (Start/Resume) Water Shut-Off				
Notice of Intent Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete					Well Integrity Other
Change Plans Plug and Abandon Temporarily At					
Final Abandonment Notice Convert to Injection Plug Back Water Disposal					
following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1.) Tag top of existing CIBP @ 4,490', POOH w/ tbg. RIH w/ CIBP & tbg to 3,980' set BIBP @ 3,980 circ mud & mix pump 25sx cmt plug on top of CIPB. POOH w/ tbg, RUWL & perf gun RIH, perf sqz holes @ 3,395', POOH & RDWL. RIH w/ pkr & tbg to 3,300' set pkr est inj rate - pressure up to 1200# & held. POOH w/ tbg & pkr SDFN. 2.)MIX & pump 35sx cmt plug @ 3,450. POOH & WOC 4 hours, RIH w tbg & tag top of cmt plug @ 3,288', POOH w/ tbg RUWL & perf gun. perf & sqz @ 1,975' POOH & RDWL, pu pkr & RIH w/ pkr & tbg to 1,700' set pkr est inj rate - pressure up to 1300# & hold. Mix & pump 35sx cmt plug @ 2,025 POOH w/ tbg & WOC 4 hours RIH w/ tbg & tag top of cmt plug @ 1,748' POOH lay down tbg RUWL & perf gun RIH					
& perf sqz @ 225' back to surf. Dig out & cut off wellhead 3' BGL weld on steel plate & dry hole i					
					MAY 2 2008 JAMOS
14 I hereby certify that the foreg	oing is true and correct		<u></u>		BUREAU OF LAND MANAGEMENT
Kristin Hodge	015		Title	Regulatory Analyst	CARLSBAD FIELD OFFICE
Signature State Signature			Date	0	04/28/2008
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by					
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					

Title 18 USC Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.