

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <input checked="" type="checkbox"/> 30-025-00025 <input checked="" type="checkbox"/>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> <input checked="" type="checkbox"/>
2. Name of Operator Oxy USA WTP LP <i>Vintage Petroleum LLC</i>		6. State Oil & Gas Lease No. S-9943
3. Address of Operator 4008 N. Grimes PMB 269 Hobbs, New Mexico 88240		7. Lease Name or Unit Agreement Name: State AD <input checked="" type="checkbox"/>
4. Well Location Unit Letter <u>P</u> : <u>366</u> feet from the <u>south</u> line and <u>991</u> feet from the <u>east</u> line Section <u>22</u> Township <u>10S</u> Range <u>32E</u> NMPM County <u>Lea</u>		8. Well No. <u>3</u>
		9. Pool name or Wildcat Mescalero San Andres <input checked="" type="checkbox"/>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

All requirements have been met for final abandonment.

P/A'd.

OK TO RELEASE.
6/6/2008
MJB

RECEIVED

MAY 28 2008

HOBBS OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tony Summers TITLE HES Tech DATE 05/23/2008

Type or print name Tony Summers

Telephone No. 575-397-8236

(This space for State use)

APPROVED BY Mateo Brown TITLE COMPLIANCE OFFICER DATE 6/6/2008

Conditions of approval, if any:

COMPLIANCE OFFICER

NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation

Field Inspection
"Preserving the Integrity of Our Environment"

RECEIVED

MAY 28 2008

HOBBS OCD

24-Jan-2008

Vintage Petroleum LLC

PO Box 4294

Houston, TX 77210

UL S-T-R
P-22-10S-32E

Property Name
State AD

API Well No.
30-025-00025-00-00

Well No.
003

Form C-103, Report of Plugging has been approved as to plugging of the Well Bore. Liability under bond is retained until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been remediated, filled and leveled.
2. Rat hole and cellar have been filled and leveled.
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been remediated, leveled and cleared of all junk & equipment.
7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned Wells have been inspected.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Signature Tony Summers Title HES TECH Date 5-23-08
Print Name Tony Summers

Oil Conservation Division • 1625 N. French Drive • Hobbs, New Mexico 88240
Phone: (505) 393-6161 • Fax (505) 397-0720 • <http://www.emnrd.state.nm.us>