State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERVATI	OITDITIDIOIT		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. F Santa Fe, NM	Tunets B1.	LL API NO. 30-025-07458	
DISTRICT II	,		indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
<u>DISTRICT III</u>		6. 8	State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410			T. N. T.	NT
i -	OTICES AND REPORTS ON WELLS		Lease Name or Unit Agreeme	
	ROPOSALS TO DRILL OR TO DEEPEN OR P APPLICATION FOR PERMIT" (Form C-101) f	or such proposals.) Sec	rth Hobbs (G/SA) Unit etion 29	
1. Type of Well: Oil Well X	Gas Well Other	8 \	Well No 431	
Name of Operator Occidental Permian Ltd.		9. (OGRID No. 157984	
3. Address of Operator		10.	Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, T.	X 79323			
4. Well Location Unit Letter [: 2310	Feet From The South	330 Feet From	n The East	Line
Section 29	Township 18-S	Range 38-E	NMPM	Lea County
Section 29	11 Elevation (Show whether DF, RKB, R. 3649' GL			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	_ bbls; Construction Material		
12. Cher	ck Appropriate Box to Indicate Nature FENTION TO:		Data UENT REPORT OF	÷:
PERFORM REMEDIAL WORK	PLUG AND ABANDON RE	MEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS CO	MMENCE DRILLING OPNS.	PLUG & AI	BANDONMENT
		OINIO TEOT AND OFMENT IO	ь Г	
PULL OR ALTER CASING	Multiple Completion CA	SING TEST AND CEMENT JOI		
PULL OR ALTER CASING OTHER: A sidize well	' ' <u></u>		Р []	[]
OTHER: Acidize well	Х	HER:	<u> </u>	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, inclu	uding estimated date of st letion or recompletion.	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, inclu	uding estimated date of st	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, inclu	uding estimated date of st letion or recompletion.	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, inclu	uding estimated date of st letion or recompletion.	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, inclu	uding estimated date of st letion or recompletion.	
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbo	HER: , and give pertinent dates, include the diagram of proposed complete the diagram of proposed	uding estimated date of st letion or recompletion. APR 3 0 2008 DBBS 0	D
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellboant.	HER: , and give pertinent dates, include the diagram of proposed complete	ading estimated date of st letion or recompletion. APR 3 0 2008 DBB 00 The policy of the below-grade tank has been seen as a second control of the below-grade tank has been seen as a seco	D
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellboant.	and belief. I further certify that ar	ading estimated date of st letion or recompletion. APR 3 0 2008 APR 3 0 2008 Description of the below-grade tank has been proved	DD as been/will be
OTHER: Acidize well 13. Describe Proposed or Completed Oproposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270° 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production. I hereby certify that the information above is constructed or closed according to NMOCD guideline.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellboard.	and belief. I further certify that ar r an (attached) alternative OCI an	APR 3 7 2008 APR 3 7 2008 APR 3 7 2008 Description or below-grade tank has proved Ciate DATE	04/29/2008
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production. I hereby certify that the information above is constructed or closed according to NMOCD guideline. SIGNATURE TYPE OR PRINT NAME Mendy A.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellboard.	and belief. I further certify that ar r an (attached) alternative OCI an ITLE Administrative Asso	APR 3 2008 APR 3 2008 APR 3 2008 Description or recompletion.	CD as been/will be
OTHER: Acidize well 13. Describe Proposed or Completed Oproposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production. I hereby certify that the information above is constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbornt. strue and complete to the best of my knowledge . , a general permit	and belief. I further certify that are an (attached) alternative OCI an Administrative Associated Johnson@oxy.com	APR 3 7 2008 APR 3 7 2008 APR 3 7 2008 Departure of the property of the pro	04/29/2008 806-592-6280
OTHER: Acidize well 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. Kill well. POOH w/ESP equipmed 2. Clean out to PBTD @4270' 3. Set packer & acid treat well. 4. Perform scale squeeze. 5. RIH w/ESP equipment. 6. Return well to production. I hereby certify that the information above is constructed or closed according to NMOCD guideline. SIGNATURE TYPE OR PRINT NAME Mendy A.	perations (Clearly state all pertinent details . For Multiple Completions: Attach wellbornt. strue and complete to the best of my knowledge . , a general permit	and belief. I further certify that ar r an (attached) alternative OCI an ITLE Administrative Asso	APR 3 7 2008 APR 3 7 2008 APR 3 7 2008 Departure of the property of the pro	04/29/2008